

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 14 2011

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-37332

Release Notification and Corrective Action

nkMW 1035633291

OPERATOR

☐ Initial Report ☒ Final Report




Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Miranda Federal Tank Battery	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No.	NMLC-0029342D

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	9	17S	30E					Eddy

Latitude 32 51.019 Longitude 103 58.558

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	20bbls	Volume Recovered	25bbls
Source of Release	Circulating Pump	Date and Hour of Occurrence	07/02/2010	Date and Hour of Discovery	07/02/2010 10:00 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Union on circulating pump discharge failed to seal. The circulating pump has been repaired and put back into service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 20bbls of oil was released from the circulating pump inside the dike walls of the lined Miranda Federal Tank Battery. Due to rainwater, we were able to recover a total of 25bbls of fluid. All free fluids were recovered. Contaminated gravel has been removed from the lined facility. Clean gravel has been added as necessary. The facility has been returned to its prior condition. (The closest well location to the tank battery is the Miranda Federal #2, API # 30-015-37332, Unit G. Sec-9-T17S-R30E, 2130' FNL 2260' FEL, 32.850510 - 103.975853.)					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Signed By:  Approved by District Supervisor:			
Title: HSE Coordinator		Approval Date: AUG 04 2011		Expiration Date: NA	
E-mail Address: jrusso@conchoresources.com		Conditions of Approval: NA		Attached <input type="checkbox"/>	
Date: 06/14/2011 Phone: 432-212-2399					

* Attach Additional Sheets If Necessary

2RP-517

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@conchoresources.com]
Sent: Tuesday, June 14, 2011 10:09 AM
To: Bratcher, Mike, EMNRD; 'james_amos@nm.blm.gov'
Subject: Miranda Federal TB - C-141 FINAL REPORT
Attachments: MIRANDA FEDERAL TANK BATTERY FINAL -- DATE OF RELEASE -- 07-02-2010.pdf

For your records, please see attached the C-141 Final Report for the Miranda Federal TB release that occurred on 07/02/2010. The facility has been returned to its prior condition and the site has been closed. Have a great rest of the day.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.