

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-24636

Release Notification and Corrective Action

NMLB1122447125

OPERATOR

X Initial Report Final Report

Name of Company ExxonMobil	7673	Contact Lisa Andrews
Address P.O. Box 4358, Houston, TX 77210		Telephone No. 281-654-1125
Facility Name Avalon Delaware Unit # 226		Facility Type Production Well

Surface Owner State	Mineral Owner	Lease No.
---------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	30	20S	28E	2310	FNL	990	FWL	Eddy

Latitude 32 32.737 Longitude -104 13.353

NATURE OF RELEASE


Type of Release Oil and Produced Water	Volume of Release 14.42 bbls	Volume Recovered 4 bbls
Source of Release Flowline off of ADU # 226	Date and Hour of Occurrence 07-06-2011 11:00 A.M	Date and Hour of Discovery 07-06-2011 11:00 A.M.
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Eric Miken	Date and Hour 07-06-2011 @ 4:00 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*
Leak on 2" steel flowline due to external corrosion. Well shut in.

Describe Area Affected and Cleanup Action Taken.*
A vacuum truck and backhoe called out. Will remediate area as needed. A delmeation and remediation plan will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>Jennifer Baird</i>	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Baird	Signed By <i>Mike Bratcher</i> Approved by District Supervisor.	
Title: Compliance Supervisor	Approval Date: AUG 12 2011	Expiration Date:
E-mail Address: jennifer.w.baird@exxonmobil.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>
Date: 07-20-11 Phone: 281 654-6119	9/12/2011	

* Attach Additional Sheets If Necessary

2RP-840

ExxonMobil Production Company

P.O. Box 4358
Houston, Texas 77210-4358


Overnight Mail 1Z V7F 007 01 9094 8239

ExxonMobil
Production

July 19, 2011

C-141 Form
Avalon Delaware Unit #226
Eddy County, New Mexico

State of New Mexico
Oil Conservation Division
District II
1301 W. Grand Avenue
Artesia, NM 88210



Gentlemen:

Please find enclosed the C-141 initial report for a spill which occurred at our Avalon Delaware Unit #226. The spill of 2.45 barrels of hydrocarbon and 11.97 barrels of produced water occurred on July 6, 2011. The site will be delineated and remediated according to the New Mexico guidelines.

If you have any questions or need additional information, please contact Eric Imken at (432)596-4210, extension 14.

Sincerely,

A handwritten signature in black ink, appearing to read "JWBaird".

Jennifer W. Baird
Compliance Supervisor

JWB/lka
Enclosures

C State of New Mexico
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

Mr. Eric Imken
Mr. Doug Parks
P020A/BDT New Mexico/Spills