

INITIAL C-141

HOBBS OCD

JUN 28 2011

RECEIVED

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact John W. Gates
Address 3300 North A St. Bldg 6, Midland, TX 79705-5406	Telephone No. 505.391.3158
Facility Name MCA Well #95	Facility Type Oil and Gas

Surface Owner Federal	Mineral Owner Federal	Lease No LC-029405B
------------------------------	------------------------------	----------------------------

LOCATION OF RELEASE API# 30-025-08065-00-00

Unit Letter O	Section 20	Township 17S	Range 32E	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	----------------------

Latitude Longitude

NATURE OF RELEASE

GW 9160¹

Type of Release Crude Oil and Produced Water	Volume of Release 31bbl (10oil, 21water)	Volume Recovered (0oil, 0water)
Source of Release Hole in a 3 inch steel flow line due to suspected corrosion	Date and Hour of Occurrence 6/15/11 1200	Date and Hour of Discovery 6/21/11 1330
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Trishia Bad Bear BLM & Geoffrey Leking NMOCD	
By Whom? John Gates	Date and Hour 6/21/11 1536	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release originated from a hole in a 3 inch steel flow line due to suspected corrosion. A COPC MSO responded to the location and installed an emergency repair clamp until permanent repairs can be made. No fluids could be recovered due to sandy soil conditions..

Describe Area Affected and Cleanup Action Taken.*

The affected area is a 75' X 75' area of sandy pasture land. No fluids could be recovered due to sandy soil conditions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John W. Gates	Approved by ENV ENGR : Geoffrey Leking District Supervisor	
Title: HSER Lead	Approval Date: 06/28/11	Expiration Date: 08/28/11
E-mail Address: John.W.Gates@conocophillips.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 6/23/11 Phone: 505.391.3158	C-141 BY 08/28/11	IRP-08-11-2737

- Attach Additional Sheets If Necessary

AUG 30 2011