○ USDOT Number ○ MC/MX Number ● Name

Enter Value: AMTEX OILFIELD SERVICE

Search

Company Snapshot

AMTEX OILFIELD SERVICES INC USDOT Number: 3887277

ID/Operations | Inspections/Crashes In US | Inspections/Crashes In Canada | Safety Rating

Carriers: If you would like to update the following ID/Operations information, please complete and submit form <u>MCS-150</u> which can be obtained <u>online</u> or from your State FMCSA office. If you would like to challenge the accuracy of your company's safety data, you can do so using FMCSA's <u>DataQs</u> system.

Other Information for this Carrier

SMS Results

Licensing & Insurance

Carrier and other users: FMCSA provides the Company Safety Profile (CSP) to motor carriers and the general public interested in obtaining greater detail on a particular motor carrier's safety performance then what is captured in the Company Snapshot. To obtain a CSP please visit the <u>CSP</u> order page or call (800)832-5660 or (703)280-4001 (Fee Required).

For help on the explanation of individual data fields, click on any field name or for help of a general nature go to SAFER General Help.

The information below reflects the content of the FMCSA management information systems as of 02/16/2023.

To find out if this entity has a pending insurance cancellation, please click here.

Entity Type:	CARRIER					
Operating Status:	AUTHORIZED FOR Property Out of Servic		vice Date:	None		
Legal Name:	AMTEX OILFIELD SERV	ICES INC	·			
DBA Name:						
Physical Address:	3314 MEADOW LARK LI CARLSBAD, NM 88220	N				
Phone:	(575) 988-2182					
Mailing Address:	3314 MEADOW LARK LI CARLSBAD, NM 88220					
USDOT Number:	3887277		State Carrier ID	Number:		
MC/MX/FF Number(s):	<u>MC-1428033</u>		DUNS	Number:		
Power Units:	2			Drivers:	2	
MCS-150 Form Date:	09/23/2022		MCS-150 Milea	<u>ge (Year):</u>	1 (2021)	
Operation Classification:						
X Auth. For Hire Priv. Pass.			Non-business) State Go			
	npt For Hire	Migrant Loca		Local G		
Priva	ate(Property)	U.S. Mail Indian		Indian N	Nation	
Priv.	Pass. (Business)	Fed. Gov't				
Carrier Operation:						
× Inte	erstate	Intrastate Only (HM) Intr		Intrasta	ntrastate Only (Non-HM)	
Cargo Carried:						
General F	Freight	Liquids/Gase	s	Cher	nicals	
Household Goods Intermodal C			Com	modities Dry Bulk		
		Passengers			gerated Food	
		Oilfield Equip			erages	
Drive/Tow	Drive/Tow away Livestock		Paper Products		0	
	es, Beams, Lumber	Grain, Feed,	Hay	Utiliti		
Building N		Coal/Coke		Agric	cultural/Farm Supplies	
Mobile Ho		Meat		°,	struction	
	y, Large Objects	Garbage/Ref	use		er Well	
Fresh Pro		US Mail			RHAULER	

ID/Operations | Inspections/Crashes In US | Inspections/Crashes In Canada | Safety Rating

US Inspection results for 24 months prior to: 02/16/2023

SAFER Web - Company Snapshot AMTEX OILFIELD SERVICES INC

Total Inspections: 2 Total IEP Inspections: 0

Note: Total inspections may be less than the sum of vehicle, driver, and hazmat inspections. Go to Inspections Help for further information.

Inspections:						
Inspection Type	Vehicle	Driver	Hazmat	IEP		
Inspections	2	2	0	0		
Out of Service	1	1	0	0		
Out of Service %	50%	50%	%	0%		
Nat'l Average % as of DATE 01/27/2023*	22.05%	6.58%	4.51%	N/A		

*OOS rates calculated based on the most recent 24 months of inspection data per the latest monthly SAFER Snapshot.

Crashes reported to FMCSA by states for 24 months prior to: 02/16/2023

Note: Crashes listed represent a motor carrier's involvement in reportable crashes, without any determination as to responsibility.

Crashes:					
Туре	Fatal	Injury	Tow	Total	
Crashes	0	0	0	0	

ID/Operations | Inspections/Crashes In US | Inspections/Crashes In Canada | Safety Rating

Canadian Inspection results for 24 months prior to: 02/16/2023

Total inspections: 0

Note: Total inspections may be less than the sum of vehicle and driver inspections. Go to Inspections Help for further information.

Inspections:				
Inspection Type	Vehicle	Driver		
Inspections	0	0		
Out of Service	0	0		
Out of Service %	0%	0%		

Crashes results for 24 months prior to: 02/16/2023

Note: Crashes listed represent a motor carrier's involvement in reportable crashes, without any determination as to responsibility.

Crashes:					
Туре	Fatal	Injury	Tow	Total	
Crashes	0	0	0	0	

ID/Operations | Inspections/Crashes In US | Inspections/Crashes In Canada | Safety Rating

The Federal safety rating does not necessarily reflect the safety of the carrier when operating in intrastate commerce.

Carrier Safety Rating:

The rating below is current as of: 02/16/2023

Review Information:

Rating Date:	None	Review Date:	None
Rating:	None	Туре:	None

SAFER Home | Feedback | Privacy Policy | USA.gov | Freedom of Information Act (FOIA) | Accessibility | OIG Hotline | Web Policies and Important Links | Plug-ins

Federal Motor Carrier Safety Administration 1200 New Jersey Avenue SE, Washington, DC 20590 • 1-800-832-5660 • TTY: 1-800-877-8339 • Field Office Contacts

2/17/23, 3:13 PM

Notes

eDOCKET | Company Name: AMTEX OILFIELD SERVICES INC Nicholas Karns LOGOUT **Company Summary**

HOME

Cases List DBA History Certification

Company Rules Authority

Docs List

Insurance Hist. Inspection Fees Fees

ndustry Type FRANSPORTATION	Industry Sub Type GENERAL COMMODITIES/PROPERTY	Ownership Type CORPORATION		
Certification Status CERTIFIED	Current Address? YES	Master Name Currrent? YES		
Company Name	AMTEX OILFIELD SERVICES INC	AMTEX OILFIELD SERVICES INC		
Address (Street 1st Line) / Mailing	3314 MEADOW LARK LN	3314 MEADOW LARK LN		
Street (2nd Line)				
City CARLSBAD	State NM	Zip 88220-0000		
County EDDY	Phone # 575-361-2509	Company Code		
Equipment Storage Location 3314 Meadow Lark LN, Carlsbad, NM 88220				

Station Points

Owner Information				
Owner Name	CARLOS GUILLEN			
Address (Street 1st Line) / Physical	3314 MEADOW LARK LN			
Street (2nd Line)				
City CARLSBAD	State NM	Zip 88220-0000		
Phone # 575-361-2509	Email CESAR@AMTEXOILFIELD.COM			

Agent / Attorney Information						
Agent (Attorney) Name	Oscar Nieto	Oscar Nieto				
Agent (Attorney) Name (2nd)						
Address (Street 1st Line)	7011 CHOLLA RD					
Street (2nd Line)						
City Carlsbad	State NM	Zip 88220-0000				
Phone # 979-415-4415	Email CESAR@AMTEXOILFIELD.COM	Last Update 01/11/2023	Updated By GARCIA, JUSTIN			

Comp	any's Current Case List (10 records)					
Case #	Case Company Name (Address)	Case Type	File Date	Туре	Case Status	Disposition
<u>23-00013-</u> <u>TRM</u>	AMTEX OILFIELD SERVICES INC (3314 MEADOW LARK LN, CARLSBAD NM 88220-0000)	TRANSPORTATION	01/11/2023	PRIMARY	CLOSED	

Tips: Click Update button to update record or Delete button to delete record.

Copyright © CSI Technology Group. All rights reserved.



Learn About the CSA Prioritization Preview

FMCSA is proposing a new prioritization methodology to keep enforcement efforts focused on the carriers in most need of intervention. Learn more about these changes and how they will improve highway safety.

Visit the CSA Prioritization Preview

AMTEX OILFIELD SERVICES INC

U.S. DOT#: 3887277 Address: 3314 MEADOW LARK LN CARLSBAD, NM 88220 Number of Vehicles: 2 Number of Drivers: 2 Number of Inspections: 1

Safety Rating & OOS

Rates (As of 02/16/2023 updated daily from <u>SAFER</u>)

Not Rated

Out of Service Rates

Туре	00S %	National Avg %
Vehicle	50.0	21.4
Driver	50.0	6.0
Hazmat		4.5

Licensing and Insurance


(As of 02/16/2023 updated hourly from <u>L&I</u>)

Active For-Hire Authority					
Туре	Yes/No MC#/MX#				
Property	Yes	MC-			
		1428033			
Passenger	No				
Household Goods	No				
Broker	No				

BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)

View CSA Prioritization Preview \rightarrow Based on a 24-month record ending January 27, 2023



https://ai.fmcsa.dot.gov/SMS/Carrier/3887277/CompleteProfile.aspx?print=true

2/17/23, 3:13 PM	Safety Mea	surement System - Co	mplete SMS Profile (U.S. DOT# 3887277)	
Unsafe Driving	with HOS	with Vehicle	with	with Driver
Violations: 0	Compliance	Maint.	Drugs/Alcohol	Fitness
Safety Event	Violations: 0	Violations: 0	Violations: 0	Violations: 0
Group: No Safety	Safety Event	Safety Event	Safety Event	Safety Event
Event Grouping	Group: No Safety Event Grouping	Group: No Safety Event Grouping	Group: No	Group: No Safety Event Grouping
Avg. PU × UF: 1.5			Safety Event	
Segment: Combination Carrier			Grouping	
Investigation Results				

No Acute/Critical Violations Discovered	N/A	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered	No Acute/Critical Violations Discovered		No Acute/Critical Violations Discovered
Discovered	N/A	Discovered	Discovered	Discovered	PUBLIC	Discovered

Select a BASIC icon above to get details, or view your Complete SMS Profile.

Summary of Activities

The summary includes information on the 5 most recent investigations and 24 months of inspections and crash history.

Most Recent Investigation: Total Inspections: 1 Total Inspections without Violations used in SMS: 1 Total Inspections with Violations used in SMS: 0 Total Crashes*: 0

*Crashes listed represent a motor carrier's involvement in <u>reportable</u> <u>crashes</u>, regardless of the carrier's or driver's role in the crash. <u>Continue</u> <u>for details</u>.

Carrier Registration

Subject to General Threshold

Enforcement Cases

(Six years as of 02/16/2023 updated monthly from <u>FMCSA</u>)

No penalties found

USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A 🕰 symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

Safety Measurement System - Complete SMS Profile (U.S. DOT# 3887277)

The A symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <u>http://safer.fmcsa.dot.gov</u> and motor carrier licensing and insurance status are available at <u>http://li-public.fmcsa.dot.gov/</u>.

Coardo Information				HOME
Search Information			1	Home
Entity Details				
Business ID#:	6951511	Status:	Active	
Entity Name:	Amtex Oilfield Services, Inc.	Standing:	Good Standing	
DBA Name:				
Entity Type and State of Dor	nicile			
Entity Type:	Foreign Profit Corporation	State of Incorporation:	Texas	
Benefit Corporation:	Νο	Statute Law Code:	53-17-1 to 53-17-20	
Formation Dates				5
Reporting Information				13
Period of Existence and Purp	oose and Character of Affairs			5
Outstanding Items				
Reports:				
No Pending Reports.				
Registered Agent:				
No Records Found.				

License:

No Records Found.

Contact InformationMailing Address314 Meadow Lark LN, Carlsbad, NM 88220Principal Place of Business in New
Mexico314 Meadow Lark LN, Carlsbad, NM 88220Secondary Principal Place of
Business in New MexicoNot ApplicablePrincipal Office Outside of New
Mexico207 Ridge Harbor Drive, Spicewood, TX 78669Registered Office in State of
Incorporation207 Ridge Harbor Drive, Spicewood, TX 78669

Principal Place of Business in Domestic State/ Country: **207 Ridge Harbor Drive, Spicewood, TX 78669**

Principal Office Location in NM: Not Applicable

Registered Agent Information	on			
Name:	Carlos Guiller	ı		
Geographical Location Address:				
Physical Address:	3314 Meadov Carlsbad, NM		Mailing Address:	3314 Meadow Lark LN, Carlsbad, NM 88220
Date of Appointment:	08/29/2022	I	Effective Date of Resignation:	
Director Information				
Title Name		Address		
Director Carlos Guil	len	3314 Meadow Lar	k LN, Carlsbad, NM 88220	
Officer Information				
Title Na	ame	Address		
Executive Director Ce	esar Tomas	C. Petra Santa 73	19, Chihuahua, Chihuahua 312	216 Mexico
Organizer Information				
Not Applicable				
Incorporator Information				
Not Applicable				
Trustee Information				
Not Applicable				
Filing History				3
				-
License History				L
	Back	Entity Name Histo	ry Return to Search	

2/17/23, 3:13 PM

Corporations Division