

INITIAL C-141

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Quantum Resources	Contact	Martin Williams
Address	4000 N. Big Spring, Suite 305 Midland, TX 79705	Telephone No.	(432)269-8667
Facility Name	Northeast Pearl Queen #13 AD	Facility Type	Well (API Number: 3002520580)
Surface Owner	Aline Sims	Mineral Owner	
		Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	23	19S	35E	1980	North Line	990	East Line	Lea

Latitude 32°38'52.423"N Longitude 103°25'21.463"W

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	<20 bbls	Volume Recovered	0 bbls
Source of Release	Well head	Date and Hour of Occurrence	8/12/2011	Date and Hour of Discovery	8/12/2011 approx 5:00 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Phone message was left at NMOCD District Office I		
By Whom?	Martin Williams, Quantum Resourced	Date and Hour	8/12/2011 5:30 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.* No.




Describe Cause of Problem and Remedial Action Taken.*

On 8/12/2011, the tubing on the well head leaked releasing less than 20 bbls of produced water. The well was shut in on the same day and the tubing repaired.

Describe Area Affected and Cleanup Action Taken.*

The lease pad surrounding the well head was scraped to remove the wet soil. The area off the pad was sampled for chlorides and screened in the field with a photoionization detector.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Martin Williams	Approved by: 	ENV ENCL: 
Title: Safety and Environmental Coordinator	Approval Date: 08/19/11	Expiration Date: 10/19/11
E-mail Address: Mwilliams@qracq.com	SUBMIT FINAL - C141 BY	1RP-8-11-2734
Date: 8/17/2011	Conditions of Approval: Created with	Attached <input type="checkbox"/>
Phone: (432) 269-8667		

* Attach Additional Sheets If Necessary



nitro

PDF

professional

download the free trial online at: nitropdf.com/professional