

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

NOV 10 2011

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

N/KMW1105342842

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No.	(432) 685-4332
Facility Name	Electra Federal #5	Facility Type	Flowline

Surface Owner: Federal	Mineral Owner	Lease No. API 30-015-34211
------------------------	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	17S	30E					Eddy

Latitude N 32 50.373° Longitude W 103 57.919°

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release 8 bbls	Volume Recovered 6 bbls
Source of Release: Flow line	Date and Hour of Occurrence 2/9/11	Date and Hour of Discovery 2/9/11 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Due to freezing temperatures the flow line split and release fluid. We replaced the split joint of pipe and returned the line to service.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech inspected and assessed the spill area for extents. A work plan was prepared and submitted to NMOCD for approval. Soils exceeding the RRAL were removed and transported to proper disposal. Once excavated to the appropriate depths, the excavation was backfilled with clean soil. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for COG)	Approved by District Supervisor 	
Title: Project Manager	Approval Date: NOV 15 2011	Expiration Date: N/A
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 10/12/11	Phone: (432) 682-4559	

Attach Additional Sheets If Necessary

2RP-610