

District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

n/KMW/1101257328

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Stephens & Johnson Operating Co.	Contact	Mike Kincaid
Address	P.O. Box 2249, Wichita Falls, Tx. 76307	Telephone No.	(940) 723-2166
Facility Name	East Millman Unit No. 150	Facility Type	Tank Battery

Surface Owner.	State	Mineral Owner		Lease No.	30-015-02257
----------------	-------	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	15	19S	28E					Eddy

Latitude N 32.65456° Longitude W 104.15868°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	Unknown	Volume Recovered	N/A
Source of Release	Vent Line	Date and Hour of Occurrence	N/A	Date and Hour of Discovery	N/A
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?		Date and Hour	3/15/10 4:59 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully \*

N/A

Describe Cause of Problem and Remedial Action Taken. \*

A vent line was located west of the East Millman Tank Battery, which periodically vented gas and small amounts of oil into an earthen pit Venting would occur due to vessel malfunction or emergencies. The pit contained free oil on top of rain water. The vent line has been connected to a holding tank to capture any fluids during periodic venting in the future

Describe Area Affected and Cleanup Action Taken \*

Tetra Tech inspected site and collected samples to define spills extent Soil that exceeded RRAL was removed and hauled away for proper disposal A liner was installed at four foot and the site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature.	OIL CONSERVATION DIVISION		
Printed Name: Ike Tavarez	Signed By <u>Mike Kincaid</u> Approved by District Supervisor.		
Title Project Manager	Approval Date	NOV 21 2011	Expiration Date: N/A
E-mail Address. Ike.Tavarez@TetraTech.com	Conditions of Approval: <u>Final</u>		Attached <input type="checkbox"/>
Date: 8-5-11	Phone (432) 682-4559		

\* Attach Additional Sheets If Necessary

2PA-551