1R - 425 - 102

GENERAL CORRESPONDENCE

YEAR(S):

13

Hansen, Edward J., EMNRD

From:Hansen, Edward J., EMNRDSent:Tuesday, February 28, 2012 5:04 PMTo:Hack ConderCc:Leking, Geoffrey R, EMNRD; 'Katie Jones'Subject:Remediation Plan (1R425-102) Further Information Required - ROC Vacuum J-33 EOL Site

RE: Junction Box Final Report for the Rice Operating Company's Vacuum J-33 EOL Site Unit Letter J, Section 33, T17S, R35E, NMPM, Lea County, New Mexico Remediation Plan (1R425-102) Further Information Required

Dear Mr. Conder:

The New Mexico Oil Conservation Division (OCD) has received Rice Operating Company's (ROC) report for the above-referenced site (dated March 30, 2011). The report indicates that additional information is required:

ROC must determine chloride concentrations in the vadose zone greater than 12 bgs at the site. ROC must submit to the OCD the investigation results within 180 days.

1

If you have any questions regarding this matter, please contact me at 505-476-3489.

Edward J. Hansen Hydrologist Environmental Bureau