


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

n.m. 1208053839

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC <i>129137</i>	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 31-13	Facility Type	Well location

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-37497
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section 31	Township 25S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32 04.821 Longitude 104 07.083

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20bbls	Volume Recovered	None
Source of Release	Poly water line	Date and Hour of Occurrence	02/10/2012	Date and Hour of Discovery	02/10/2012 6:00 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Heat from a gas fire melted a nearby poly produced water line causing the release. The bad section of the poly line has been replaced.

Describe Area Affected and Cleanup Action Taken.*
Initially roughly 20bbls were released from the poly line and we were unable to recover any fluid with a vacuum truck. The spill area is located in the pasture area off of the well location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Josh Russo	Signed By Approved by District Supervisor:	
Title:	HSE Coordinator	Approval Date:	MAR 20 2012
E-mail Address:	jrusso@conchoresources.com	Expiration Date:	
Date:	02/23/2012	Phone:	432-212-2399
		Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:
4/20/12

2RP-1059

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Friday, March 02, 2012 3:22 PM
To: Bratcher, Mike, EMNRD
Cc: Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject: C-141 Initial Report - Myox 31 State com 13H
Attachments: img-302171650-0001.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 02-10-2012 at the Myox 31 state com 13H.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system.
Thank you

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.