

3R – 436

C-141

DATE:

06/14/2011

Bermudez, Brianna, EMNRD

From: VonGonten, Glenn, EMNRD
Sent: Friday, July 13, 2012 3:52 PM
To: Bermudez, Brianna, EMNRD
Subject: FW: Review Revised C141s
Attachments: Revised c141 LAT 6C GW 110311.pdf; Revised c141 Jacques Gas Com F#1 GW 110311.pdf

Glenn von Gonten

Senior Hydrologist
Environmental Bureau
Oil Conservation Division
Energy, Minerals and Natural Resources Department
1220 South St. Francis Drive
Santa Fe, New Mexico 87505
505-476-3488
Fax-476-3462
glenn.vongonten@state.nm.us
<http://www.emnrd.state.nm.us/ocd/>

From: Tami Ross [<mailto:tross@animasenvironmental.com>]
Sent: Wednesday, November 09, 2011 1:02 PM
To: VonGonten, Glenn, EMNRD; Powell, Brandon, EMNRD
Subject: Review Revised C141s

Glenn and Brandon,

Please see attached revised C 141 forms for the Enterprise Lateral 6C and Jacques Gas Com F#1 groundwater impact. On behalf of Enterprise, Animas Environmental will submit a copy of the initial release response report and groundwater investigation workplan for each site to your offices. Hard copies will be mailed once they have been reviewed and published in our office.

If you have any questions please call Ross Kennemer at 505-564-2281.

Thank you,

Tami C. Ross, CHMM
Project Manager
Animas Environmental Services
Phone: 505-564-2281
Cell: 505-793-2072

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Enterprise Products Operating, LP	Contact Aaron Dailey	
Address 614 Reilly Avenue, Farmington, NM 87401	Telephone No. (505) 599-2286	
Facility Name Jacquez Gas Com F#1 Gathering Line	Facility Type Natural Gas Gathering Pipeline	
Surface Owner Private	Mineral Owner Private	API No.

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	4	29N	9W					

Latitude_N36deg45.105' Longitude_W107deg47.454'

NATURE OF RELEASE

Type of Release Natural Gas	Volume of Release Unknown	Volume Recovered All free product was removed from location and groundwater has cleaned up to well below standard
Source of Release 4" natural gas gathering line	Date and Hour of Occurrence Initial leak location discovered on 7.27.2011 @ 1700 hours	Date and Hour of Discovery Groundwater results received 10.24.2011 @ 11:14 hours
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Glenn Von Gonten	
By Whom? Ross Kennemer, Animas Environmental Services	Date and Hour 10.26.2011 @ 11:14 hours	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Pipeline repairs were completed 10.10.2011. Soil and groundwater investigation activities were conducted on 10.10.2011. Contaminated soil and groundwater were removed from the excavation for line repair access. Soil and grab samples were collected for laboratory analysis. Upon receipt of laboratory reports and analysis, a site investigation workplan was submitted to NM OCD on 11.9.2011. Landowner granted access to conduct groundwater sampling on 3.15.2012 in accordance with EPA approved methods. Analytics demonstrate that the nominal amount of residual constituents that were sloughed off into the groundwater at the time the repairs were made and groundwater sampling was done have degraded. Please find the attached Groundwater Investigation Report dated June 11, 2012 prepared by Animas Environmental Services.

Describe Area Affected and Cleanup Action Taken.*

Please find the attached Groundwater Investigation Report dated June 11, 2012 prepared by Animas Environmental Services. No further action is recommended at this site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Aaron Dailey		Approved by Environmental Specialist:	
Title: Environmental Scientist		Approval Date:	Expiration Date:
E-mail Address: amdailey@eprod.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6.14.2012 Phone: (505) 599-2286			

* Attach Additional Sheets If Necessary

COPY TO OCD AZTEC