


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1219552251 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ West Coop Trunkline	Facility Type	Trunkline

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-25492 *
				Wells tied into trunkline	30-015-03163

LOCATION OF RELEASE GJ West Coop Unit 74

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	28	17S	29E					Eddy

Latitude 32 48.700 Longitude 104 04.642

NATURE OF RELEASE

Type of Release	Produced water w/ skim oil	Volume of Release	10bbls	Volume Recovered	2bbls
Source of Release	Trunkline	Date and Hour of Occurrence	07/09/2012	Date and Hour of Discovery	07/09/2012 3:20 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					



Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused a hole to develop in our GJ West Coop Unit #74 and #125 trunkline. We are in the process of replacing the corroded steel flowline.

Describe Area Affected and Cleanup Action Taken.*

Initially approximately 10bbls were release from the corroded flowline and we were able to recover 2bbls with vacuum truck. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Signed By: 	
Title: HSE Coordinator		Approval Date: JUL 13 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/12/2012 Phone: 432-212-2399			

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

8/13/12

2RP-1227

Bratcher, Mike, EMNRD

From: Joshua Russo [jrusso@concho.com]
Sent: Thursday, July 12, 2012 9:11 AM
To: Bratcher, Mike, EMNRD
Cc: Tavarez, Ike; Dorey, Kim; Franklin, Tom K.
Subject: C-141 Initial Report - GJ WEST COOP UNIT TRUNKLINE
Attachments: GJ WEST COOP UNIT TRUNKLINE (74,125) -- DATE OF RELEASE -- 07-09-2012.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 07/09/2012.

Thank you,

Joshua Russo

HSE Coordinator
550 W. Texas Ave, Suite 100
Midland, Texas 79701
Phone: (432) 683-7443
Cell: (432) 212-2399
jrusso@conchoresources.com



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.