


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nJMW/217254/25 OPERATOR Initial Report Final Report

Name of Company	Oxy Permian	Contact	Chris Jones
Address	1502 W. Commerce Drive	Telephone No.	575-449-3337
Facility Name	Parakeet 29 Battery	Facility Type	Gathering
Surface Owner	Mineral Owner		APR Lease No. <i>30-015-35140</i>

LOCATION OF RELEASE *Parakeet 29 Fed #1*

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	29	19S	27E	1535	S	662	E	Eddy County, NM

Latitude N 32.62853 Longitude W 104.29463

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	5 bbls	Volume Recovered	0 bbls
Source of Release	Load line failure	Date and Hour of Occurrence	4/24/12 @ 8:00 am	Date and Hour of Discovery	4/24/12 @ 2:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD; Jennifer Van Curen-BLM		
By Whom?	Leslie Moreno	Date and Hour	4/25/12 @ 8:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A load line rupture caused 5 bbls of condensate to spill onto the ground. Recovery was not possible due to evaporation. No remediation was needed because this battery is lined with a plastic liner.

Describe Area Affected and Cleanup Action Taken.*

The area affected was contained in the lined battery. No remediation was needed because this battery is lined with a plastic liner.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chris Jones	Signed By <i>Mike Bratcher</i> Approved by District Supervisor:		
Title: HES Specialist	Approval Date: AUG 24 2012	Expiration Date: <i>NA</i>	
E-mail Address: Christopher Jones@oxy.com	Conditions of Approval: <i>NA</i>	Attached <input type="checkbox"/>	
Date: 08/23/2012	Phone: (575) 449-3337	<i>Final</i>	

* Attach Additional Sheets If Necessary

2RA-1178

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Friday, August 24, 2012 6:55 AM
To: 'Kathy Purvis'; jvancure@blm.gov
Cc: christopher_jones@oxy.com; kswinney@bbcinternational.com;
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com
Subject: RE: Final C-141 Parakeet #29 Battery

C-141 has been received.

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Kathy Purvis [<mailto:kathy@bbcinternational.com>]
Sent: Thursday, August 23, 2012 11:17 AM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: christopher_jones@oxy.com; kswinney@bbcinternational.com; cbrunson@bbcinternational.com;
jgilkey@bbcinternational.com
Subject: Final C-141 Parakeet #29 Battery

Attached is the final C-141 for Oxy's Parakeet #29 Battery. If you have any questions, please contact me and reply with receipt notification. Thank you.

Kathy Purvis
BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Thursday, August 23, 2012 11:17 AM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: christopher_jones@oxy.com; kswinney@bbcinternational.com;
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Final C-141 Parakeet #29 Battery
Attachments: Final C-141 signed and sent to OCD and BLM.pdf

Attached is the final C-141 for Oxy's Parakeet #29 Battery. If you have any questions, please contact me and reply with receipt notification. Thank you.

Kathy Purvis

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com