


District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1720 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action
OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Anemone ANE Federal #2	API Number 30-015-27982	Facility Type Gas well
		Order Number 2RP- 765
Surface Owner Federal	Mineral Owner Federal	Lease No. NM - 78214

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	9	22S	24E	1090	NORTH	840	WEST	EDDY

NATURE OF RELEASE

Type of Release Water	Volume of Release 22 PW	Volume Recovered 22 PW
Source of Release Equipment failure on pumps and alarms	Date and Hour of Occurrence 4/22/2011	Date and Hour of Discovery 4/22/2011 - PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOC D/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 4/25/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Dump Valve failed caused liquid in supply line to backup oil tanks. Crew onsite was able to stop flow and pick up fluids.		
Describe Area Affected and Cleanup Action Taken.* An approximate size of 30' x 8' was impacted. The impacted area is located behind the tanks. Soil from the pooling areas was excavated and disposed of at an NMOC D approved facility. Vertical and horizontal delineation samples will taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water: >100' (approx. 585', per New Mexico State Engineers Office); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by District Supervisor	
Title: Environmental Scientist	Approval Date: 11/6/12	Expiration Date: N/A
E-mail Address: atrujillo@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Thursday, October 18, 2012	Phone: 575-748-4310	

* Attach Additional Sheets If Necessary

2RP-765