


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

11MLB/125229542

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Alamo Permian Resources, LLC.	Contact	Steven Mastin
Address	415 W. Wall St. Suite 500	Telephone No.	(432) 557-5847
Facility Name	Empire J Federal #3	Facility Type	

Surface Owner: Federal	Mineral Owner: Federal	API No.	30-015-00169
------------------------	------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	18S	26E	2304	N	330	E	Eddy

Latitude N 32.77233° Longitude W 104.32915°

NATURE OF RELEASE

Type of Release: Oil and Water	Volume of Release EST 5 bbls oil and 15 bbls of water	Volume Recovered 0 bbls
Source of Release: 500 bbl Frac Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 8/16/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Cause of problem: TBD

Remedial Action Taken: Clean up per Tetra Tech's environmental assessment and agreement with current BLM procedures and regulations; To prevent future discharges, frac tank was removed all fluids are being produced to a berm contained tank battery.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech personal inspected the site and collected samples to define the spill extents. Soil exceeding the RRAL was removed and hauled to Lea Land Inc. for proper disposal. Confirmation samples were taken and then the site was brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report for NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Ike Tavarez (agent for Alamo)	Approved by Signed By		
Title: Project Manager	Approval Date: NOV 19 2012	Expiration Date: N/A	
E-mail Address: Ike.Tavarez@TetraTech.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 6-12-12 Phone: (432) 682-4559			2RP-879

* Attach Additional Sheets If Necessary