

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

NOV 26 2012

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Chesapeake Operating, Inc.	Contact	Bradley Blevins
Address	PO Box 190, Hobbs, NM 88241	Telephone No.	(575) 391-1462
Facility Name	WTU #622	Facility Type	Well location
Surface Owner	Mineral Owner	Lease No. API#30-025-01743	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	16	20S	33E	1980	North	1980	West	Lea County, NM

Latitude 32.57515° Longitude 103.67064°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	5 bbls
Source of Release	Broken line	Date and Hour of Occurrence	11/16/2012	Date and Hour of Discovery	11/16/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking- NMOCD		
By Whom?	Cliff Brunson for Bradley Blevins	Date and Hour	11/19/2012 @ 4:19 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A broken line caused 15 bbls of produced water to leak onto the ground. 5 bbls of produced water were recovered via vacuum truck and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The areas affected are approximately 115' x 10' and 190' x 30'. 5 bbls of produced water were recovered via vacuum truck. Further remediation will be performed in accordance with a NMOCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor:  Environmental Specialist	
Title: EHS Specialist	Approval Date: 11/27/12	Expiration Date: 01/28/13
E-mail Address: Bradley.blevins@chk.com	Conditions of Approval: SUBMIT FINAL	Attached <input type="checkbox"/>
Date: 11/26/12	C-141 BY 01/28/13	IRP-11-12-2874
Phone: (575) 391-1462		

* Attach Additional Sheets If Necessary

NOV 29 2012