

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

NOV 29 2012

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Bob Akin	
Address: 2130 W Bender Blvd Hobbs, NM	Telephone No.: 575-738-1739	
Facility Name: Humphrey Queen Unit Battery - HQU 16	Facility Type: Battery / Producer	
Surface Owner: Private	Mineral Owner: Private	API No.: 3002520612

LOCATION OF RELEASE

Unit Letter K	Section 03	Township 25S	Range 37E	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line West	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 32.15747437982 Longitude: -103.152868409041

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls	Volume Recovered: 0
Source of Release: Steel pipeline	Date and Hour of Occurrence: 11/23/2012 9:30am	Date and Hour of Discovery: 11/23/2012 10am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking- OCD Trish Bad Bear- BLM	
By Whom? Gary Wink	Date and Hour 11/24/2012 10:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: 3 inch steel line blew out due to age and corrosion. shut in valves, and replaced line.		
Describe Area Affected and Cleanup Action Taken.* : Spill area approx. 20' x 20' further remedial action pending....		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Bob Akin</i>	Approved by District Supervisor: <i>Geoffrey Leking</i> Environmental Specialist	
Printed Name: Bob Akin	Approval Date: 12/04/12	Expiration Date: 02/04/13
Title: Production Forman	Conditions of Approval: SUBMIT FINAL	
E-mail Address: rakin@linenergy.com	Attached <input type="checkbox"/>	
Date: 11/29/2012 Phone: 405-264-3405	C-141 BY 02/04/13 IRP-12-12-2876	

* Attach Additional Sheets If Necessary

DEC 04 2012