

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 28 2013

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW1303834128
Name of Company Merit Energy Company 14591
Address 2004 Ave. O Eunice N.M. 88210
Facility Name WSU 19-2 SWU
Shugart West 19 Fed #002
Surface Owner BLM Mineral Owner BLM API No. Nm.Nm.093772

LOCATION OF RELEASE

API # 30-015-36501

Unit Letter	Section 19	Township 18-S	Range 31-E	Feet from 660	North/South Line SOUTH	Feet from the 1930	East/West Line EAST	County Eddy
-------------	---------------	------------------	---------------	------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7247 Longitude -103.9063

NATURE OF RELEASE

Type of Release Produce water	Volume of Release 12-15 bls.	Volume Recovered approx 8 +-
Source of Release From frac tank being fed by injection well	Date and Hour of Occurrence 1-28-13	Date and Hour of Discovery 1-28-18 /6:40 A.M.
Was Immediate Notice Given? Required x x <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? BLM /James Amos/Terry Gregston OCD / Mike Bratcher	
By Whom? Chris Flores	Date and Hour 1-28-2013 1st call 7:42 a.m. 2nd call 808 a.m. 3rd call 8:19 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes xx <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* N.A.		
Describe Cause of Problem and Remedial Action Taken.* Trucking Company inattention, driver quit and relief was not sent in for replacement. Stress importance of communication.		
Describe Area Affected and Cleanup Action Taken.* Area approximately 70 ft x15 ft wide On location only, around frac tanks. Pick -up water that pooled up . Will scrape up all dirt down to clean surface and bring in clean caliche to replace. To haul contaminated dirt to proper disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Chris Flores		OIL CONSERVATION DIVISION
Printed Name: Chris Flores		Approved by Environmental Specialist Signed By Mike Bratcher
Title: Production Foreman		Approval Date: FEB 07 2013 Expiration Date:
E-mail Address: chris.flores@meritenergy.co		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: March 2013 Attached <input type="checkbox"/>

2RP-1540

Date: 1-28-2013
575-420-5506

Phone:

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Flores, Chris <Chris.Flores@meritenergy.com>
Sent: Monday, January 28, 2013 7:46 PM
To: Bratcher, Mike, EMNRD
Cc: Flores, Chris
Subject: WSU 19-2 spill report 1-28-2013
Attachments: WSU 19-2 frac tank O.C.D. c-141.doc