


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW130654179

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	GJ WEST COOP UNIT NORTH	Facility Type	TANK BATTERY

Surface Owner	STATE	Mineral Owner		Lease No. (API#)	30-015-26743
---------------	-------	---------------	--	------------------	--------------



LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	17S	29E					EDDY

Latitude 32.82102 Longitude 104.07601

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	15bbls	Volume Recovered	11bbls
Source of Release	Plug seal failed on valute covering on transfer pump	Date and Hour of Occurrence	02-22-2013	Date and Hour of Discovery	02-22-2013 7:00am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The valute covering had the wrong material for the plug. Replaced the failed plug with a stainless plug.					
Describe Area Affected and Cleanup Action Taken.*					
Initially an estimated 15bbls were released due to a faulty seal on the transfer pump. We were able to recover 11bbls with a vacuum truck. All free fluids have been recovered. The entire spill was contained inside the facility walls. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor: Signed By 	
Title: Senior Environmental Coordinator		Approval Date: MAR 06 2013	Expiration Date:
E-mail Address: jrusso@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 03-04-2013 Phone: 432-212-2399			

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:

April 6, 2013

2RP-1575

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Monday, March 04, 2013 4:06 PM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Tavarez, Ike; tom.k.franklin@tetrattech.com
Subject: C-141 Initial report GJ WEST COOP UNIT NORTH TANK BATTERY
Attachments: GJ WEST COOP UNIT NORTH TANK BATTERY -- DATE OF RELEASE -- 02-22-2013.pdf

Mr. Bratcher,

Please see attached a C-141 Initial Report for a release that occurred at our GJ WEST COOP UNIT NORTH TANK BATTERY in Eddy County New Mexico. We plan to assess the spill inside the facility timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com

Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.