

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 03 2013

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	DODD FEDERAL UNIT #10 B (580)	Facility Type	TANK BATTERY
Surface Owner	FEDERAL	Mineral Owner	
		Lease No. (API#)	30-015-39278

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	10	17S	29E					EDDY

Latitude 32.84282

Longitude 104.05513

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15bbls	Volume Recovered	14bbls
Source of Release	1/4" valve at circulating pump	Date and Hour of Occurrence	03-19-2013	Date and Hour of Discovery	03-19-2013 3:00pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Roustabout crew making repairs to circulating pump left open a 1/4" valve. Roustabout need to pay more attention and close valve to prevent further release.

Describe Area Affected and Cleanup Action Taken.\*

Initially 15bbls of oil were released from a 1/4" valve that was left open and we were able to recover 14bbls with a vacuum truck. All free fluid has been recovered. The spill was contained within the lined facility. Contaminated gravel has been removed and we have replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Josh Russo	Approved by District Supervisor:		
Title: Senior Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: jrusso@concho.com	Conditions of Approval:		Attached: <input type="checkbox"/>
Date: 03-25-2013	Phone: 432-212-2399		

\* Attach Additional Sheets If Necessary

2RP-1613

Accepted for record  
NMOCD

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Wednesday, April 03, 2013 1:11 PM  
**To:** Bratcher, Mike, EMNRD; Amos, James <jamos@blm.gov> (jamos@blm.gov)  
**Cc:** Tavaréz, Ike; tom.k.franklin@tetrattech.com; Joshua Russo  
**Subject:** C-141 Initial/Final Report - Dodd Federal Unit #10B  
**Attachments:** DODD FEDERAL UNIT #10 B -- DATE OF RELEASE -- 03-19-2013.pdf

Gentlemen,

Please see attached the C-141 Initial / Final Report for a release that occurred at our Dodd Federal Unit #10B on 03/19/2013. This is a lined facility.

Thank you,

*Robert Grubbs Jr.*  
*Sr. Environmental Coordinator*  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.