

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

MAY 06 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 1.16 on back
side of form

Release Notification and Corrective Action

JMW1312742172

OPERATOR☒ Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Osprey BPS State #1-H	API Number 30-015-37552	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. VA-7312
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 32	Township 25S	Range 26E	Feet from the 660	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.08078 Longitude 104.32211

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 360 B/PW	Volume Recovered 320 B/PW
Source of Release Discharge water pump	Date and Hour of Occurrence 4/26/2013; AM	Date and Hour of Discovery 4/26/2013; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD District II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 4/26/2013; AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Discharge water pump failed to start because generator not operational. Generator started up to begin produced water transport. Vacuum trucks called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 30' X 30' (outside of production pad). Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (118', Section 22, T25S-R26E, NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: > 1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Robert Asher

Title: NM Environmental Regulatory Supervisor

E-mail Address: boba@yatespetroleum.com

Date: Monday, May 06, 2013

Phone: 575-748-4021

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By

MAY 07 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

Attached ☐

June 7, 2013

2RP-1645

* Attach Additional Sheets If Necessary



New Mexico Office of the State Engineer

Wells with Well Log Information

(A CLW#### in the
POD suffix indicates
the POD has been
replaced & no longer
serves a water right,
file.)

(R=POD has
been replaced,
O=orphaned,
C=the file is
closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

													(in feet)						
													Depth	Depth		License			
POD Number	Code	Subbasin	County	Source	6416	4	Sec	Tws	Rng	X	Y	Start Date	Finish Date	Log File Date	Well	Water	Driller	Number	
<u>C 01013</u>	C		ED	Shallow			4	25	25S	26E	571505	3551456*	06/10/1961	06/17/1961	07/12/1961	245		HOWARD HEMLER	24
<u>C 01089</u>	C		ED	Shallow	3	4	1	03	25S	26E	567505	3558398*	08/06/1962	08/07/1962	08/17/1962	96	45	ABBOTT, FLOYD	46
<u>C 01368</u>	C		ED	Shallow	1	1	22	25S	26E	567261	3554059*	06/15/1967	06/19/1967	08/01/1967	143	118	SMITH, A.F.	28	
<u>C 02675</u>	C		ED	Shallow	1	4	1	09	25S	26E	565907	3556978*	02/09/2000	02/15/2000	03/01/2000	180	45	BILL DUBOSE, JR.	1107
<u>C 03285</u>	C		ED	Shallow	4	4	2	07	25S	26E	563713	3556658	05/27/2006	05/27/2006	05/31/2006	84	60	MALEY, JASON R.	1314

Record Count: 5

PLSS Search:

Township: 25S

Range: 26E

*UTM location was derived from PLSS - see Help

The data is furnished by the NM/OSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

5/2/13 3:53 PM

Page 1 of 1

WELLS WITH WELL LOG INFORMATION



FACSIMILE TRANSMITTAL SHEET

FROM:
Robert Asher**TO:**
Mike Bratcher/NMOCD II**DATE:**
Monday, May 06, 2013**FAX NUMBER:**
9-748-9720**TOTAL NO. OF PAGES INCLUDING COVER:**
3**RE:**
C-141; Osprey BPS State #1-H**NOTES:****COMMENTS:**

☐ URGENT ☒ FOR REVIEW ☐ PLEASE COMMENT ☐ PLEASE REPLY ☐ PLEASE RECYCLE

NOTES/COMMENTS:**INITIAL REPORT.**

This report is for a 4/26/2013 release.

If you have any questions, contact me at 575-748-4217.

Thank you.

Robert Asher

Environmental Regulatory Department

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Friday, April 26, 2013 8:42 AM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Osprey BPS State #1-H)

Yates Petroleum Corporation is reporting a release at the following location (4/26/2013).

Osprey BPS State #1-H
30-015-37552
Section 32, T25S-R26E
Eddy County, New Mexico

Released: Approximately 250 B/PW; Recovered: IN PROCESS.

Release was discovered this morning (4/26/2013). Cause of release is unknown at this time. Release is contained within a lined/bermed battery. Vacuum truck(s) have been called and recovering produced water.

A Form C-141 Initial/Final will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
