


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1312749580

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	HONEYGRAHAM / GRAHAM NASH	Facility Type	GATHERING LINE

Surface Owner	STATE	Mineral Owner	APIK	Lease No. (API#) 30-15-38488 HG #6 (API#) 30-15-38595 HG #7 38c 28 → (API#) 30-15-37498 GN #1
---------------	-------	---------------	------	---

LOCATION OF RELEASE Assign to H96 30-015-38488

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	26S	28E					EDDY

Latitude 32 01.178 Longitude 104 06.968

32.019597 NATURE OF RELEASE 104.116122

Type of Release	Produced water	Volume of Release	100bbls	Volume Recovered	40bbls
Source of Release	Gathering line	Date and Hour of Occurrence	04/15/2013	Date and Hour of Discovery	04/15/2013 5:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	04/16/2013 10:41am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" water gathering line fractured possibly due to sun fatigue and age. The 4" gathering line has been replaced.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 100bbls were released due to a fracture in a 4" gathering line in the pasture. We were able to recover 40bbls of produced water using a vacuum truck. The gathering line included the Honey Graham #6&7 and Graham Nash #1. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	
Printed Name:	Robert Grubbs Jr.
Title:	Senior Environmental Coordinator
E-mail Address:	rgrubbs@concho.com
Date:	04-30-2013
Phone:	432-661-6601

OIL CONSERVATION DIVISION

Approved by District Supervisor:	Signed By
Approval Date:	MAY 07 2013
Expiration Date:	
Conditions of Approval:	Attached <input type="checkbox"/>
Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

June 7, 2013

2RP-1647

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Tuesday, April 30, 2013 1:55 PM
To: Bratcher, Mike, EMNRD
Cc: Joshua Russo; Tavaréz, Ike; tom.k.franklin@tetrattech.com
Subject: C-141 Initial Report - Honey Graham / Graham Nash (Gathering Line)
Attachments: HONEY GRAHAM- GRAHAM NASH (GATHERING LINE) -- DATE OF RELEASE -- 04-15-2013.pdf

Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred on 04-15-2013 at our Honey Graham / Graham Nash (Gathering Line) in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.



Google earth



Lat/long for HG 1 has to be obs in RBDMS


32° 01' 10.55"
104° 06' 58.04"

32.019597
104.116122

Conv on C-141

HG 6	104.099697	104.099697
32.019549	32.018697	
104.110608		
HG 7	104.117030	104.117030
32.018631	32.022239	
104.112749		
HG 1	HG 2	
32.018610	32.020073	
104.117029	104.111676	

29-26s-28e



Oil Conservation Division

MapNotes

DrawnBy

4/30/2013 4:03:21 PM

Bratcher, Mike, EMNRD

From: Michelle Mullins <MMullins@concho.com>
Sent: Tuesday, April 16, 2013 9:41 AM
To: 'Amos, James'; Bratcher, Mike, EMNRD
Cc: Joshua Russo; Robert Grubbs
Subject: Honey Graham 29 State #1H-Immediate Notification

Mr. Amos, Mr. Bratcher:

On 04/15/2013 at approximately 5:00 pm, a produced fluid release was discovered at the above-referenced location. An estimated 100 bbls of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report.

GPS coordinates, legal description and driving directions are below.

N 32.019633 W 104.116133

Honey Graham 29 State #1H
Sec. 29 T26S R28E
330' FNL & 660' FWL
Eddy County, NM
API 30-015-37465

Off Highway 285 south of Malaga, turn west onto White City Road (MM 5). Travel 3 miles, turn south. Travel 3 miles, turn east. Travel 200 yards to location.

Michelle Mullins
HSE Field Technician
COG Operating, LLC
(432) 934-1052
mmullins@concho.com

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.