


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*nJMW 1317737425*

OPERATOR:  Initial Report  Final Report

Name of Company-Cimarex Energy	Contact- James Tinney
Address-600 N Marienfeld Ste 600, Midland Tx 79701	Telephone No. 575 706 0095
Facility Name-Dozier Federal Com 1	Facility Type- Tank battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

**LOCATION OF RELEASE** *API# 30-015-10804*

Unit Letter	Section 14	Township 19S	Range 31E	Feet from the 1980	North/South Line south	Feet from the 1980	East/West Line west	County - Eddy
-------------	------------	--------------	-----------	--------------------	------------------------	--------------------	---------------------	---------------

Latitude- 32.6591N Longitude- 103.8429W

**NATURE OF RELEASE**

Type of Release- crude oil	Volume of Release-235bbls	Volume Recovered-20 bbls
----------------------------	---------------------------	--------------------------

Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM) Mike Bratcher (OCD..left message)
--	--

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe Fully.\* *(\*Please include API#\*)*

Describe Cause of Problem and Remedial Action Take  
*6/16/13 Pumper arrived on location and noticed oil around bottom of tanks. Pumper called me and I notified Terry Ainsworth (Cimarex), Jim Amos @ BLM and Mike Bratcher @ OCD (Left Message). Could not see any visible signs where oil leaked out of oil tank. Spill was contained inside unlined containment.*

Describe Area Affected and Cleanup Action Take  
*Around oil tanks inside containment. Emptied oil tank with hole, picked up standing oil. Talon to do assessment and work plan.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: James Tinney	Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Production Foreman	Approval Date: <b>JUN 26 2013</b>	Expiration Date:
E-mail Address: jtinney@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>

Date: 6-17-13 Phone: 575-706-0095

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION PROPOSAL NO LATER THAN: July 26, 2013**

*2RP-1689*

\* Attach Additional Sheets If Necessary