

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1321142719

OPERATOR

Initial Report Final Report

Name of Company	Enterprise Field Services LLC	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Box Canyon 4A Line	Facility Type:	Gas Gathering Pipeline
Surface Owner	Mineral Owner	NA	Lease No.
			NA

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	23	21S	21E					Eddy

Latitude: N 32.285618 Longitude: W -104.464206

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	214 MCF	Volume Recovered	0
Source of Release	Pipeline Blow-down to cap and abandon.	Date and Hour of Occurrence (Start)	04/22/2013@10:06 MDT	Date and Hour of Discovery (End)	04/22/2013@11:06
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The affected section of the 4-inch line was isolated and blown-down to abandon the tie-in line.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Matthew E. Marra	Approved by District Supervisor:	Accepted for record NMOCD
Title:	Senior Director, Environmental	Approval Date:	JUL 30 2013
E-mail Address:	memarra@eprod.com	Expiration Date:	
Date:	5-1-2013	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	432-686-5404		

* Attach Additional Sheets If Necessary

fJMW 1321142552

iJMW 1321142892

2RP-1777



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

May 1, 2013



7012 3460 0001 7236 4231
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the April 22, 2013 release from our Box Canyon 4A Line in our Carlsbad Gathering Field, Eddy County. The line was blown down to abandon the tie-in line.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Matthew E. Marra
Senior Director, Environmental

/sjn
attachments