

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJM 1320431669

OPERATOR Initial Report Final Report

Name of Company SM ENERGY COMPANY 154903	Contact VICKIE MARTINEZ
Address 3300 N "A" STREET, BLDG 7-200	Telephone No. (432)688-1709
Facility Name PDU INJECTION STATION	Facility Type BATTERY

Surface Owner BLM	Mineral Owner BLM	API No. 3001530026
--------------------------	--------------------------	---------------------------


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	35	19S	29E	1330	NORTH	180	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 7 BBLS	Volume Recovered 0 BBLS
Source of Release PRODUCED WATER TRANSFER LINE	Date and Hour of Occurrence 5/31/13 2:30 PM	Date and Hour of Discovery SAME
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM & NMOCD	
By Whom? RYAN HARRISON	Date and Hour 5/31/13 2:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
CONTRACTOR WAS DRAGGING A FRESH WATER TRANSFER LINE ACROSS THE PDU PRODUCED WATER TRANSFER LINE AND CAUSED A CUT IN THE PRODUCED WATER TRANSFER LINE NEXT TO THE LEASE ROAD. REPAIR WAS MADE AND SOIL REMEDIATED AND PAID FOR BY CONTRACTOR

Describe Area Affected and Cleanup Action Taken.*
SPILL AREA: 100'X3' = 300 SQ FT. SPILL WAS CLEANED UP AND PAID FOR BY CONTRACTOR

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Vickie Martinez</i>	OIL CONSERVATION DIVISION	
Printed Name: VICKIE MARTINEZ	Approved by Environmental Specialist: Signed By <i>Mike Brandon</i>	
Title: ENGINEER TECH II	Approval Date: JUL 23 2013	Expiration Date:
E-mail Address: VMARTINEZ@SM-ENERGY.COM	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 07/16/2013 Phone: (432)688-1709	August 23, 2013 2RP-1739	

* Attach Additional Sheets If Necessary