

**RECEIVED**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

JUL 23 2013 State of New Mexico  
Energy Minerals and Natural Resources

**NMOCD ARTESIA**

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nJW 132 836233

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company - Devon Energy	Contact - Mike Braswell
Address - 6488 Seven Rivers Hwy - PO Box 250	Telephone No. - 575-513-8223
Facility Name - Turquoise PWU 27 - 5H	Facility Type: C-144 Permitted Surface Impoundment

Surface Owner	Mineral Owner	Lease No. API # 30-015-40583
---------------	---------------	------------------------------

**LOCATION OF RELEASE**

Unit Letter A	Section 27	Township 19S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.6362188 N Longitude -104.054923 W

**NATURE OF RELEASE**

Type of Release - Produced Water	Volume of Release Unknown	Volume Recovered Unknown
Source of Release - Poseidon Modular Impoundment	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? -	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Elevated chloride levels under Poseidon Modular Impoundment.

Describe Area Affected and Cleanup Action Taken.\*

Area underlying Poseidon Modular Impoundment excavated between 3-6 inches. See attached Report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Mike Braswell		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Mike Braswell		Approved by District Supervisor: Signed By Mike Braswell	
Title: Completion Consultant - RG Inc.		Approval Date: AUG 06 2013	Expiration Date:
E-mail Address: Mike.Braswell@dmn.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/27/2013 Phone: 575-513-8223			

\* Attach Additional Sheets If Necessary

2RP-1788