

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

*Remediation
in Progress*
*Remedy Part of BLM
told James Tinney this
was all state*

Form C-141
Revised October 10, 2003
2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1321848019

OPERATOR Initial Report Final Report

Name of Company-Cimarex Energy <i>215099</i>	Contact- James Tinney
Address-600 N Marienfeld Ste 600, Midland Tx 79701	Telephone No. 575 706 0095
Facility Name-VERMAJO SWD#1	Facility Type- DISPOSAL FLOW LINE

Surface Owner <i>FED</i>	Mineral Owner	Lease No. <i>30-015-40644</i>
--------------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter <i>O</i>	Section 15	Township 17 S	Range 28 E	Feet from the 900	North/South Line south	Feet from the 2530	East/West Line east	County - Eddy
-------------------------	---------------	------------------	---------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude- 32.829636 Longitude- -104.163492

NATURE OF RELEASE

Type of Release- PW	Volume of Release-40 bbls	Volume Recovered-0 bbls
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<i>Release date 7/27/13 confirmed 8/6/13 via phone call</i> If YES, To Whom? JIM AMOS(BLM) MIKE BRATCHER(OCD)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
AUG 01 2013
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Take
Pumper was leaving Vermejo SWD 1 when he found a leak in the poly line coming from the Pere Marquette 18 battery. He went to Pere Marquette 18 batt And made sure pump was off. Called out crew to repair poly line.

Describe Area Affected and Cleanup Action Take
40' x 1' wide area to the south of the ROW and 100yard x 2-3' wide along ROW. Water ran off and was nothing to pick up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>James Tinney</i>	OIL CONSERVATION DIVISION	
Printed Name: James Tinney	Approved by District Supervisor:-	Signed By <i>Mike Bratcher</i>
Title: Assistant Production Foreman	Approval Date: AUG 06 2013	Expiration Date:
E-mail Address: jtinney@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/31/13 Phone: 575-706-0095	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>September 06, 2013</i>	

* Attach Additional Sheets If Necessary

2RP-1789