


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Release Notification and Corrective Action

NJM 1322841395

OPERATOR Initial Report Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: JL Keel A Battery - JL Keel A #9	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No.: 3001505097
------------------------	----------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	07	17S	31E	1980	North	1980	East	Eddy

Latitude: 32.85081 Longitude: -103.90604

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 40bbls	Volume Recovered: 35bbls
Source of Release: Water Tank	Date and Hour of Occurrence: 08/14/2013 11:30am	Date and Hour of Discovery: 08/14/2013 11:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NM OCD M. Burton-BLM	
By Whom? Brian Wall	Date and Hour 08/14/2013 3:15pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: pulled up on location to get guages, noticed inside the firewalls had water. Walked around and noticed water tank overflowing. Never received any alarm for pump failure or high tank level. Turned H.O.A. switch on panel box to transfer pump to hand position pump turned on and pumped down tank. Called electrician (Dixie Electric) to diagnose problem found transmitter on back of tank was bad causing it to show water level in tank at a steady 3 foot.

Describe Area Affected and Cleanup Action Taken.* : called vacuum truck (Unique Vacuum Services) to pick up standing water 60bbls of rain water and produced water. unable to determine exact amount of rain water mixed in with produced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor Signed By <i>Mike Bratcher</i>	
Title: Construction Foreman II	Approval Date: AUG 16 2013	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 08/15/2013 Phone: 806-367-0645	Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets if Necessary

SEPTEMBER 16, 2013

2RP-1839


Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Thursday, August 15, 2013 3:32 PM
To: Bratcher, Mike, EMNRD; mburton@blm.gov
Cc: Fitzwater, Nancy; Callahan, Terry; Moreno, Laura; Butters, Thomas; Golding, Chris; Wall, Fred
Subject: Linn- JL KEEL A Battery 8-14-13
Attachments: JL Keel A Battery 8-14-13.pdf



Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.