District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

MAY 2 0 2013

RECEIVED

Form C-141 Revised August 8, 2011

NMOCD ARTES appropriate District Office in with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action												
MM	132	1462	(2	10		OPERA		[Initia	l Report		
Name of Co		Chevron U		4323			David A. Pagar					
						Telephone No. wk: 575-396-4414X275 cell: 505-787-9816						
Facility Name Skelly 907 BTY 5./4/3						Facility Type Oil Production Batteries						
Surface Owner Federal BLM Mineral Owner						Federal API No.						
SKU 907 BTY (CTB) - Latitude: 32.819634 / Longitude: -103.872881 LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County		
J	22	17S	31E				·				Eddy	
Type of Release Gases to a Flare Source of Release Flare						OF RELEASE Volume of Release 1573.33 MSCF Date and Hour of Occurrence			Volume Recovered 0 MSCF Date and Hour of Discovery			
						05/14/13 06:00PM			05/14/13 06:00PM			
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom?						
By Whom?						Date and Hour						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.* N/A												
Describe Cause of Problem and Remedial Action Taken.* Frontier shut in sales line to complete maintenance at Maljamar Gas Plant causing Chevron to curtail gas at the battery. Flared for 24 hours and Frontier line was back online at 07:00AM on 05/17/13.												
Describe Are	Describe Area Affected and Cleanup Action Taken.*											
Shut in wells to minimize flaring. Stayed in close contact with frontier so we stopped flaring as soon as they are able to accept our gas in the sales line.												
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
n -1 P						OIL CONSERVATION DIVISION						
Signature: David A. Pagano A						Approved by Environmental Specialist: Accepted for record NMOCD						
		nmental Spec	cialist			Approval Dâ	EP 0 3 20	13 E	Expiration I	Date:		
E-mail Addre	ess: dpgn(@chevron.co	n			Conditions o				Attached		
Date: 05/1												
Attach Addi	tional Shee	ts If Necess	ary							711	0-1885	

FJMW 1321131421 iJMW 1324636860

1000 $\sim N$

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) < David.Pagano@chevron.com>

Sent: Friday, May 17, 2013 2:17 PM

To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD

Cc: Moschetti, Nick (NMOS); DeLeon, Josepha

Subject: Final C141 report for flaring at SKU 907 on 05/14/13 – 05/17/13

Attachments: 20130514 C-141 Skelly 907 Bty Flare FS.pdf

Mr. Bratcher,

Here is the final C-141 for the flaring that occurred at our SKU 907 Battery on 05/14/13 - 05/17/13 due to the gas purchaser shutting us in to complete maintenance.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown) 56 Texas Camp Rd., Lovington, NM 88260

a Phone: 575-396-4414 x275

 a Cell: 505-787-9816

 □ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."