


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1324639813

OPERATOR Initial Report Final Report

Name of Company	Chevron USA Inc. <i>4323</i>	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	Skelly 907 BTY <i>5-19-13</i>	Facility Type	Oil Production Batteries
Surface Owner	Federal BLM	Mineral Owner	Federal
		API No.	

SKU 907 BTY (CTB) - Latitude: 32.819634 / Longitude: -103.872881

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	22	17S	31E					Eddy

NATURE OF RELEASE

Type of Release	Gases to a Flare	Volume of Release	1400 MSCF	Volume Recovered	0 MSCF
Source of Release	Flare	Date and Hour of Occurrence	05/19/13 11:00AM	Date and Hour of Discovery	05/19/13 11:00AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.* N/A
Describe Cause of Problem and Remedial Action Taken.*
Frontier shut in sales line to complete maintenance at Maljamar Gas Plant causing Chevron to curtail gas at the battery. Flared for 16 hours and Frontier line was back online at 03:00AM on 05/20/13.

Describe Area Affected and Cleanup Action Taken.*
Shut in wells to minimize flaring. Stayed in close contact with frontier so we stopped flaring as soon as they are able to accept our gas in the sales line.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>David Pagano</i>	OIL CONSERVATION DIVISION	
Printed Name: David A. Pagano	Approved by Environmental Specialist:	Accepted for record NMOCD
Title: Health & Environmental Specialist	Approval Date: SEP 03 2013	Expiration Date:
E-mail Address: dpgn@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/20/13 Phone: 505-787-9816		

* Attach Additional Sheets If Necessary

fJMW 1321131421

iJMW 1324640160

2RP-1886

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) <David.Pagano@chevron.com>
Sent: Monday, May 20, 2013 12:09 PM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha
Subject: Final C141 report for flaring at SKU 907 on 05/19/13 – 05/20/13
Attachments: 20130519 C-141 Skelly 907 Bty Flare FS.pdf

Mr. Bratcher,

Here is the final C-141 for the flaring that occurred at our SKU 907 Battery on 05/19/13 – 05/20/13 due to the gas purchaser shutting us in to complete maintenance.

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."