


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMW 1325656033

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit 140 Tank Battery	Facility Type: Exploration and Production

Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-105-29876
----------------------------	----------------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 32	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.263302 Longitude W 103.910493

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 10 Bbbls crude oil and 50 Bbbls produced water	Volume Recovered: None
Source of Release: 3" water transfer poly line	Date and Hour of Occurrence: 9-9-13, time unknown	Date and Hour of Discovery: 9-9-13 time 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 9/9/13 at approx. 1:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The 3" poly line failed at a welded connection. The pump was not running at the time of discovery, produced water was gravitating from the tank onto the ground outside the tank containment area, the tank valve was closed and the line was repaired.

Describe Area Affected and Cleanup Action Taken.* Approximately 3334 sq. ft. of pasture and approximately 1162 sq. ft. of road was affected by the release. All of the fluid had soaked into the ground. A one-call will be placed and the saturated soil will be scraped up and stockpiled on-site. A remediation plan will be submitted to the NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: Signed By Mike Brannon	
Title: Waste Management and Remediation Specialist	Approval Date: SEP 11 2013	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: 9/10/93	Phone: 432-556-8730	

* Attach Additional Sheets If Necessary

October 13, 2013

2RP-1907