


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

nJMK 1319333284

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Chevron USA Inc. 4323	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	TexMack BTY	Facility Type	Oil Production Batteries
Surface Owner	Federal	Mineral Owner	Federal
		API No. 30-015-29720) Closest Well Texmack 11-1)	

Latitude: 32.853570 / Longitude: -103.843080

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	11	17S	31E	990	North	1650	West	Eddy

NATURE OF RELEASE

Type of Release	Vent	Volume of Release	1800MSCF	Volume Recovered	0 MSCF
Source of Release	Vent	Date and Hour of Occurrence	06/26/13 10:00AM	Date and Hour of Discovery	06/26/13 10:00AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.*					
VRU down at the battery due to the motor failing. After motor replaced the drive malfunctioned and was subsequently repaired. Vented a total of 864hrs and a total of 1,800mcf.					
Describe Area Affected and Cleanup Action Taken.*					
N/A					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCd rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCd marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCd acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: David Pagano		OIL CONSERVATION DIVISION			
Printed Name: David A. Pagano		Approved by Environmental Specialist: Signed By Mike Deane			
Title: Health & Environmental Specialist		Approval Date: SEP 04 2013 Expiration Date:			
E-mail Address: dpagn@chevron.com		Conditions of Approval:			
Date: 08/02/13 Phone: 505-787-9816		Attached <input type="checkbox"/>			

* Attach Additional Sheets If Necessary

Closed Since
SEP 04 2013

2RP-1714

Bratcher, Mike, EMNRD

From: Pagano, David (David.Pagano) <David.Pagano@chevron.com>
Sent: Friday, August 02, 2013 9:09 AM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha; Schwartzengraber, E Faithe
Subject: Final C141 report for venting at TexMack Battery
Attachments: 20130626 C-141 TexMack Bty Vent FS.pdf

Mike,

Here is the final report for this event.

David A. Pagano

MCA Health & Environmental Specialist (Central Permian – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."

From: Pagano, David (David.Pagano)
Sent: Tuesday, July 02, 2013 10:55 AM
To: Pagano, David (David.Pagano); Bratcher, Mike, EMNRD
Cc: Moschetti, Nick (NMOS); DeLeon, Josepha; Schwartzengraber, E Faithe
Subject: Initial C141 & C-129 report for flaring at TexMack Venting

Mr. Bratcher,

Here is the initial C-141 & C-129 for the venting at our TexMack Central Tank Battery that started on 6/26/13 due to the VRU going down when the motor failed. We are expecting to have a replacement motor for the VRU installed by the end of this week or early next week. Once we are back online I will send you the final report. Please let me know if you have any questions or need additional information.

Here are the Associated Wells producing into the TexMack:

TEXMAK 11 FED 10
TEXMAK 11 FED 11
TEXMAK 11 FED 15
TEXMAK 11 FED 27
TEXMAK 11 FED 28
TEXMAK 11 FED 32
TEXMAK 11 FED 39
TEXMAK 11 FED 41
TEXMAK 11 FED 42
TEXMAK 11 FED 57
TEXMAK 11 FED 61

Regards,

David A. Pagano

MCA Health & Environmental Specialist (Oil Area – Vacuum/Buckeye, Dollarhide & Sundown)

56 Texas Camp Rd., Lovington, NM 88260

☎ Phone: 575-396-4414 x275

☎ Cell: 505-787-9816

☎ Fax: 575-396-6913

dpgn@chevron.com

"CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email."