

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1333039224

OPERATOR ☒ Initial Report ☒ Final Report

Name of Company OXY USA WTP LP 16696	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING FACILITY

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE


Type of Release Gas	Volume of Release 11985.75 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 11/6/2013 12:20:00 AM	Date and Hour of Discovery 11/6/2013 12:20:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MIKE BRATCHER	
By Whom? RODNEY CAMPBELL	Date and Hour 11/06/2013 11:13 A.M. VOICEMAIL	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A	RECEIVED NOV 12 2013
--------------------------------------------------------	--------------------------------

Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED INLET GAS THROUGH CRYO BY-PASS VALVE DUE TO BROKE NIPPLE ON AMINE RECYCLE FLOW CONTROL TRANSMITTER. Remedial Action Taken: OPERATIONS SHUT DOWN HIGH PRESSURE PUMPS IN ORDER TO STOP LEAK AND LOSS OF AMINE, AND CALLED OUT OPERATIONS CREW TO REPAIR LEAK.	NMOCD ARTESIA
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------

Describe Area Affected and Cleanup Action Taken.* N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:	Accepted for record NMOCD
Title: HES Specialist	Approval Date: NOV 26 2013	Expiration Date:
E-mail Address: RODNEY.CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-8-13	Phone: (575) 628-4167	

* Attach Additional Sheets If Necessary

fJMW1327034125 jJMW1333042609

Like approval by
BLM

2RP-2080