


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1334331071

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 217955	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Tankless 35 Federal #001	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-36784

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	35	22S	31E					Eddy

Latitude 32.35303

Longitude 103.75480

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	3bbls of oil 10bbls of produced water	Volume Recovered	0bbls of oil 0bbls of produced water
Source of Release	Heater treater	Date and Hour of Occurrence	11-24-2013	Date and Hour of Discovery	11-20-2013 10:00a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Gasket failed on heater treater due to corrosion. Replaced gasket to prevent future spills.					
Describe Area Affected and Cleanup Action Taken.*					
Initially an estimated 3bbls of oil and 10bbls of produced water were released from a gasket that failed on a heater treater. We were unable to recover any fluids. The release was contained on location. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a work plan to the NMOC D for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs Jr.</i>	Approved by District Supervisor Signed By <i>Mike Brannon</i>	
Printed Name: Robert Grubbs Jr.	Approval Date: DEC 09 2013	Expiration Date:
Title: Senior Environmental Coordinator	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	
E-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 11-27-2013 Phone: 432-661-6601		


* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
January 9, 2013

2RP-2100

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Wednesday, December 04, 2013 4:06 PM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Tavarez, Ike; Kujawski, Marcus (Marcus.Kujawski@tetrattech.com)
Subject: C-141 Initial Report - Tankless 35 Federal #001 (TB)
Attachments: Tankless 35 Federal #001 (TB) -- Date of Release -- 11-24-2013 Initial.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our Tankless 35 Federal #001 (TB) on 11-24-2013 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

***Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com***

***Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701***



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.