

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

NOV 22 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NTMW 1333639525

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	OGRID Number	Contact	
Yates Petroleum Corporation	25575	Lupe Carrasco	
Address		Telephone No.	
104 S. 4 TH Street		575-748-1471	
Facility Name	API Number	Facility Type	
Penasco Water System		Water Line	
Surface Owner	Mineral Owner	Lease No.	
Fee	Fee		

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	25	18S	25E					Eddy

Latitude 32.14868 Longitude -104.4441094

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	25 B/PW	20 B/PW
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Water Line	11/4/13 PM	11/4/13 PM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Mike Bratcher, NMOCD II	
By Whom?	Date and Hour	
Bob Asher, Yates Petroleum	11/5/13 PM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	
If a Watercourse was Impacted, Describe Fully.*		
N/A		
Describe Cause of Problem and Remedial Action Taken.*		
Cause of the release was due to a break in a water line. Line was isolated and shut in. Vacuum truck dispatched to recover standing fluid. Crews called in to repair line. Backhoe dispatched to excavate impacted area.		
Describe Area Affected and Cleanup Action Taken.*		
An approximate area of 12' X 100' was impacted. Impacted soils to be scraped up and taken to an NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX, Chlorides will be run for documentation. If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted. Depth to Ground Water: >100' (approximately 125', Section 25-T18S-R25E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Lupe Carrasco</i>		OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco		Approved by District Supervisor: Signed By <i>Mike Bratcher</i>	
Title: Environmental Regulatory Agent		Approval Date: DEC 02 2013	Expiration Date:
E-mail Address: lcarrasco@yatespetroleum.com		Conditions of Approval:	
Date: Friday, November 22, 2013 Phone: 575-748-1471		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

NTMW 1333639377
NTMW 1333641427

January 2, 2014

2RP-2086

Bratcher, Mike, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Tuesday, November 05, 2013 3:42 PM
To: Bratcher, Mike, EMNRD; Dade, Randy, EMNRD
Cc: Amber Cannon; Katie Parker; Lupe Carrasco
Subject: Release (Penasco Water System)

Yates Petroleum Corporation is reporting a release at the following location (11/4/2013).

Penasco Water System
SW/4 of Section 25, T18S-R25E
Eddy County, New Mexico

Released: 25 B/PW; Recovered: 20 B/PW.

Cause of release is from a water line. Vacuum truck was called and impacted soils were excavated. The surface owner is Remuda Energy Transportation. Complete information will be submitted in a Form C-141.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
