

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

JMW 133 5341610

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	LRE Operating, LLC 281994	Contact	Michael Barrett
Address	1111 Bagby Street, Suite 4600, Houston, TX 77002	Telephone No.	575-623-8424
Facility Name	Kersey State Battery	Facility Type	Production Battery

Surface Owner	C.O.G.	Mineral Owner	State	API No.	30-015-30889
---------------	--------	---------------	-------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	32	17S	28E	844'	South	330'	East	Eddy County, NM

Latitude 32.786054 Longitude 104.190396

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	10 bbls	Volume Recovered	5 bbls
Source of Release	Heater Treater Gasket	Date and Hour of Occurrence	12/12/13 @ noon	Date and Hour of Discovery	12/12/13 @ 1pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Heater treater gasket blew out, spraying oil onto ground and some vegetation outside of berms.
Picked up standing fluid.

Describe Area Affected and Cleanup Action Taken.*

There was some moisture on the ground due to rain.
Native vegetation and caliche soil.
Pick up heavy contaminated soil with hydrovac. Treat with Micro Blaze.

RECEIVED

DEC 17 2013

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Michael Barrett	Approved by Environmental Specialist:	Signed By: Mike Brannon	
Title: Production Supervisor	Approval Date: DEC 19 2013	Expiration Date:	
E-mail Address: mbarrett@limerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 12/16/13 Phone: 575-623-8424	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:		

* Attach Additional Sheets If Necessary

January 19, 2013

2RP-2122