Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office	Revised November 3, 2011
Office <u>District I</u> District I Intervention District I District I Distric	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 MAR 26 2014 1220 South St. Francis Dr.	30-025-28685 ~
	5. Indicate Type of Lease STATE S FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM RECEIVED 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	SEVEN RIVERS QUEEN UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other INJECTION	8. Well Number 064
2. Name of Operator	9. OGRID Number
LINN OPERATING INC	269324
3. Address of Operator	10. Pool name or Wildcat
600 TRAVIS, SUITE 5100, HOUSTON, TX 77002	LANGLIE MATTIX;7 RVRS-Q-GRAYBURG
4. Well Location	
Unit Letter <u>E: 2310</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u>	line
Section 02 Township 23S Range 36E NMPM LEA Count	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3466'	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	ata
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR	— — — — — — — — — — — — — — — — — — — —
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	— — —
OTHER:	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Ope	
K Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	concrete. It shows the
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU</u>	JARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIC	ON HAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, prod	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC	All fluids have been removed from non-
retrieved flow lines and pipelines.	d lines have been removed from longe and well
If this is a one-well lease or last remaining well on lease: all electrical service poles an location, except for utility's distribution infrastructure.	a filles have been removed from lease and wen
When all work has been completed, return this form to the appropriate District office to sch	*
SIGNATURE Find Ramson-Viper Serve TITLE Prod. MNg TYPE OF PRINT NAME	<u> </u>
	PHONE:
For State Use Only	
APPROVED BY: Manuel Jour TITLE Compliance	Office DATE 4/1/2014
Conditions of Approval (if any):	
v	APR-0-3 2014
	ALLA

APR-0-3	2
---------	---