

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87418
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

FEB 14 2014

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
NMOCD ARTESIA
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NHMP 1406951035

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Tracy Kidd
Address PO Box 250 Artesia, NM 88211	Telephone No. 575-513-0628
Facility Name Remuda Basin SWD 1	Facility Type Salt Water Disposal Well
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-29549	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	20	23S	30E	330	North	660	West	Eddy

Latitude: 32.2966716 Longitude: -103.90964

NATURE OF RELEASE

Type of Release Spill	Volume of Release 10Bbbls	Volume Recovered 4Bbbls
Source of Release mechanical failure	Date and Hour of Occurrence 02.11.2014 11:30 AM	Date and Hour of Discovery 02.11.2014 11:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Aaron Kidd- Assistant Production Foreman	
By Whom? Jimmy Tarvin- Lease Operator	Date and Hour 02.11.2014 11:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*


Approximately 10 Bbbls of Produced water was discovered spilled on the west end of the Remuda Basin SWD 1 facility under the H pump. The water also flowed onto the pasture on the west side of the site. Size of area affected: 42'x120'.

Due to internal corrosion inside the 1/2 inch nipple, vibration from the pump weakened the nipple causing it to break off the suction line to the H pump. The burn on location was repaired and Globe Services recovered 4 Bbbls of the 10 Bbbls of spilled produced water via vac truck. Pump will be balanced to reduce vibration, two more braces will be installed to support discharge line and mounting brackets will be installed for the murphy switches on the pump.

Describe Area Affected and Cleanup Action Taken.*

Vac truck recovered 4Bbbls of the 10 Bbbls spilled. Talon LPE to gather soil samples for analyzing. Based on the soil sample results, the Bureau of Land management will make the determination regarding whether to remove and replace the affected soil or any other remedial actions necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sandra Farley	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 3/10/14	Expiration Date:
E-mail Address: Sandy.Farley@dmv.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 02.12.2014	Phone: 575.746.5587	

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4/10/14

2 RP 2195

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Wednesday, February 12, 2014 1:21 PM
To: Bratcher, Mike, EMNRD; Jeff Robertson (jlr Robertson@blm.gov)
Subject: C141 & photos PW spill 2.11.14 at Remuda Basin SWD 1
Attachments: C-141 Remuda Basin SWD 1- PW Spill 2.11.14.doc; Remuda Basin PW spill 2.11.14 2 of 7.JPG; Remuda Basin PW spill 2.11.14 3 of 7.JPG; Remuda Basin PW spill 2.11.14 4 of 7.JPG; Remuda Basin PW spill 2.11.14 6 of 7.JPG; Remuda Basin PW spill 2.11.14 7 of 7.JPG; Remuda Basin 2.11.14 5 of 7.JPG; Remuda Basin PW spill 2.11.14 1 of 7.JPG; Remuda Basin PW spill 2.11.14 sketch.JPG

Good afternoon,

Attached is the initial C141, pictures and sketch regarding the PW water spill that occurred at the Remuda Basin SWD 1 on February 11, 2014. Hard copies have been placed in the mail.

If I can be of any further assistance please contact me.

Have a pleasant day.

Sandra Farley
**Field Admin Support
Production**

Devon Energy Corporation
Artesia, New Mexico
6488 Seven Rivers Highway
Sandy.Farley@dvn.com
575 746 5587 (office)



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.

