


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1000 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

nHMP1407146471

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 32 State #003H	Facility Type	Flowline

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-41642
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	32	25S	28E					Eddy

Latitude 32 05.660 Longitude 104 07.012

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	18bbbls	Volume Recovered	17bbbls
Source of Release	Poly flowline	Date and Hour of Occurrence	01-17-2014	Date and Hour of Discovery	01-17-2014 4:20pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Poly crew cut into the line and squeezed off both ends. The water transfer pump kicked on building up pressure until the clamp on the upstream side failed. Shut down transfer pump and fused the line back together.

Describe Area Affected and Cleanup Action Taken.*

Initially 18bbbls of produced water were released. We were able to recover 17bbbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor:	
Title: Senior Environmental Coordinator		Approval Date: 3/12/14	Expiration Date: NA
Email Address: rgrubbs@concho.com		Conditions of Approval:	
Date: 01-24-2014 Phone: 432-661-6601		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/12/14	

Attached ☐

* Attach Additional Sheets If Necessary

2RP 2202

Bratcher, Mike, EMNRD

From: Darrell Moore <darrell.moore@entechservice.com>
Sent: Tuesday, February 18, 2014 8:01 AM
To: Bratcher, Mike, EMNRD
Cc: rmcneill@concho.com; mmullins@concho.com; atrujillo@concho.com; rgrubbs@concho.com; Shane.diller@entechservice.com; chan.patel@entechservice.com
Subject: Site Assessment Notification
Attachments: 01-17-2014 Myox 32 State #003H (FL) Initial.pdf; 01-21-2014 SRO 17 State Com (SWD) Initial.pdf; 01-22-2014 Honey Graham 29 State Com #006H (FL) Initial.pdf

Mike,


Attached, please find three C-141s for releases on Concho Oil and Gas sites. We will be doing the initial assessment on these sites beginning Thursday, February 20, 2014 at 10 am beginning at the Myox 32 State #003. This email will serve as 48 hour notice of our intentions.

If you have any questions, I can be reached at 432-266-8375 or at my email Darrell.moore@entechservice.com. Thank you for your attention to this matter.

*Darrell Moore
Regional Project Manager
EnTech Consulting Corp.
432-266-8375*

Bratcher, Mike, EMNRD

From: Robert Grubbs <RGrubbs@concho.com>
Sent: Monday, January 27, 2014 8:26 AM
To: Bratcher, Mike, EMNRD
Cc: Robert McNeill; Production Mail
Subject: C-141 Initial Report - Myox 32 Stare #003H (FL)
Attachments: 01-17-2014 Myox 32 State #003H (FL) Initial.pdf



Mr. Bratcher,

Please see attached the C-141 Initial Report for a release that occurred at our Myox 32 Stare #003H (FL) on 01-17-2014 in Eddy County New Mexico. We plan to assess the spill area timely.

Thank you,

***Robert Grubbs Jr.
Sr. Environmental Coordinator
432.683.7443 (main)
432.818.2369 (direct)
432.661.6601 (cell)
rgrubbs@concho.com
Mailing Address:
One Concho Center
600 W. Illinois Avenue
Midland, Texas 79701***



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.