


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

### Release Notification and Corrective Action

nHMP14072415-49

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: Skelly Satellite #3 - Skelly Unit 065		Facility Type: Satellite

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05342
------------------------	----------------	-----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	17S	31E	2080	North	1980	East	Eddy

Latitude: 32.8216044651195 Longitude: -103.872597423405

#### NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 6 bbls/40bbls	Volume Recovered: 0 / 30bbls
Source of Release: Pump	Date and Hour of Occurrence: 03/09/2014	Date and Hour of Discovery: 03/09/2014 7:40am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton - BLM / Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 03/10/2014 8:45am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: on top of transfer pump 1 1/2 x 2" swedge w/ 2" T w/ groove on top flat plug w/ 1/2 x 1/4 bushing, 1/4 " nipple broke off, that show pressure on trunk line, pump is vibrating, need line pump and elec. Motor.

Describe Area Affected and Cleanup Action Taken.\* : Spray outside dike to the S 20'x 20' and to the NW 20' x 40' all other fluids stay inside dike. Satellite is sitting on Skelly Unit # 65 injection well pad. Call 2 vacuum truck and call power wash gang to wash sep.header,pumps. Have Diversified delineate site. Send in PLA to OCD and BLM. After approved PLA will remove contaminated soils and haul to approved site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Brian Wall		Approved by District Supervisor:	
Title: Construction Foreman II		Approval Date: 3-13-14	Expiration Date: NA
E-mail Address: bwall@linenergy.com		Conditions of Approval:	
Date: 03/10/2014 Phone: 806-367-0645		Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4-13-14	
		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP 2210


## Bratcher, Mike, EMNRD

---

**From:** McCracken, Theresa <TMcCracken@linnenergy.com>  
**Sent:** Monday, March 10, 2014 10:22 AM  
**To:** mburton@blm.gov; Bratcher, Mike, EMNRD  
**Cc:** Callahan, Terry; Moreno, Laura; Butters, Thomas; Gonzales, EL; Hickert, Aaron; Wall, Fred; smcghee@diversifiedfsi.com; aruth@diversifiedfsi.com; mpatterson@diversifiedfsi.com; Natalie Gladden (nlgadden@diversifiedfsi.com); rpons@diversifiedfsi.com  
**Subject:** Linn- Skelly Satellite #3 3-9-14  
**Attachments:** Skelly Satellite #3 3-9-14.pdf

Please find attached the initial C-141 for the above referenced location.

Thank you,



*Theresa McCracken*

Field Administrator

**LINN Energy, LLC**

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

[tmccracken@linnenergy.com](mailto:tmccracken@linnenergy.com)

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.