


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

n HMP1408548600

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Neff Federal #1 and #3 SWD Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner	API No.30-015-28281(nearest well)
---------------	-----	---------------	-----------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	25	22S	31E					Eddy County, NM

Latitude N 32.367782° Longitude W 103.733851°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	4 bbls oil, 400 bbls produced water	Volume Recovered	400 bbls
Source of Release	High winds caused power pole trip which lead to the tanks spilling over	Date and Hour of Occurrence	03/17/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Jennifer VanCuren, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	03/18/2014 @ 9:24 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

High winds caused the power pole line fuse to trip which lead to the tanks overflowing and spilling 400 bbls of produced water and 4 bbls of oil onto the ground. A vacuum truck recovered 400 bbls of fluids and the power was restored to the battery location.

Describe Area Affected and Cleanup Action Taken.*

The affected area is 20' x 60' inside the containment area and 15' x 20' outside the containment area. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by Environmental Specialist: 		
Title: HES Specialist	Approval Date: 3-26-14	Expiration Date:	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: Remediation per OGD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION		Attached <input type="checkbox"/>
Date: 3-18-14	Phone: (575) 397-8216		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

4-26-14

2RP-2226

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Wednesday, March 19, 2014 10:38 AM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Neff Federal #1 and #3 SWD Battery
Attachments: Initial C-141, Neff Fed #1 & #3 SWD Btry.pdf

Attached is the initial C-141 for a leak that occurred at the Neff Federal #1 and #3 SWD Battery on 03/17/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Tuesday, March 18, 2014 9:24 AM
To: Bratcher, Mike, EMNRD; jvancure@blm.gov
Cc: C J Summers; Rachael_McPherson@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Kathy Purvis
Subject: Neff Federal #1 and #3 SWD Battery

This is to inform you that Oxy Permian Primary NM South had a release at the Neff Federal #1 and #3 SWD Battery on March 17, 2014. Oxy released 400 bbls of produced water and 4 bbls of oil due to high winds making the power pole trip causing the tanks to spill over. The release is located in the Northwest quarter-section of Section 25, T22S, R31E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: At the intersection of CR 29 and Mills Ranch Road, go East on Mills Ranch Road for 0.5 mile to 1st battery on your left.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com