

RECEIVED

MAR 17 2014

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
Rio Brazos Road, Aztec, NM 87410  
District IV  
S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

nHMP1408523814

## OPERATOR

☒ Initial Report☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Myox 32 State #001H	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-41641
---------------	-------	---------------	--	------------------	--------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	32	25S	28E					Eddy

Latitude 32 04.458

Longitude 104 05.434

## NATURE OF RELEASE

Type of Release Oil and produced water	Volume of Release 12bbls of oil 30bbls of produced water	Volume Recovered 10bbls of oil 30bbls of produced water
Source of Release Water tank	Date and Hour of Occurrence 03-07-2014	Date and Hour of Discovery 03-07-2014 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Michelle Mullins	Date and Hour 03-11-2014 06:58am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Water tank ran over due to water pump malfunction and high water alarm transducer was shut in. Repaired the water pump and opened the transducer.

Describe Area Affected and Cleanup Action Taken.\*

Initially 12bbls of oil and 30bbls of produced water were released. We were able to recover 10bbls of oil and 30bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:		
Printed Name: Robert Grubbs Jr.			
Title: Senior Environmental Coordinator	Approval Date: 3/26/14	Expiration Date: NA	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Final		Attached <input type="checkbox"/>
Date: 03-17-2014 Phone: 432-661-6601			


\* Attach Additional Sheets If Necessary

2RP-2224

## Bratcher, Mike, EMNRD

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Monday, March 17, 2014 1:01 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill; Production Mail  
**Subject:** C-141's Initial/Final Reports - Myox 32 State #001H (TB) - Down South State Com #001H  
**Attachments:** 03-08-2014 Down South State Com #001H (TB) Initial - Final.pdf; 03-07-2014 Myox 32 State #001H (TB) Initial - Final.pdf



**Mr. Bratcher,**

***Please see attached the C-141's Initial/Final Reports for the releases that occurred at our Myox 32 State #001H (TB) on 03-07-2014 and our Down South State Com #001H on 03-08-2014 in Eddy County New Mexico. These are lined facility***

***Thank you,***

**Robert Grubbs Jr.**  
**Sr. Environmental Coordinator**  
**432.683.7443 (main)**  
**432.818.2369 (direct)**  
**432.661.6601 (cell)**  
**[rgrubbs@concho.com](mailto:rgrubbs@concho.com)**  
**Mailing Address:**  
**One Concho Center**  
**600 W. Illinois Avenue**  
**Midland, Texas 79701**



**CONFIDENTIALITY NOTICE:** *The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.*

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

## Bratcher, Mike, EMNRD

---

**From:** Michelle Mullins <MMullins@concho.com>  
**Sent:** Tuesday, March 11, 2014 5:58 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert Grubbs  
**Subject:** Myox 32 State #1H

Mr. Bratcher:

At approximately 10:30 a.m. on 3/07/2014, a produced fluid release was discovered at the above-referenced facility. An estimated 42 barrels of produced fluid was released. The cause of the release is currently under investigation. We will follow up within 15 days with a C-141 Report. GPS coordinates, legal description and driving directions are listed below.

32.07944 104.10725

Myox 32 State #1H  
Unit O Sec. 32  
T25S R28E  
190' FSL & 1980' FEL  
Eddy County, NM  
API 30-015-41641

From Artesia, travel south on Highway 285 to White's City Road. Turn west and go past 2<sup>nd</sup> cattleguard. Turn north to fence line, turn west and follow fence approximately .3 miles. Location is on the north side of lease road.

Thank you.

Michelle Mullins  
Environmental Coordinator  
COG Operating, LLC  
(432) 934-1052  
[mmullins@concho.com](mailto:mmullins@concho.com)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.