

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JAN 27 2014

Form C-141  
Revised October 10, 2003

NMOCD ARTESIA

Submit Copy to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

n HMP1409237494

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Loco Hills SWD 35 #001	Facility Type	SWD

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-31635
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	17S	30E					Eddy

Latitude 32.78561 Longitude 103.91967

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	1/4bbl of oil 10bbls of produced water	Volume Recovered	1/4bbl of oil 10bbls of produced water
Source of Release	Load line	Date and Hour of Occurrence	01-17-2014	Date and Hour of Discovery	01-17-2014 6:45pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Driver drove off still attached to the load line. Replace the load line.

Describe Area Affected and Cleanup Action Taken.\*

Initially 1/4bbl of oil and 10bbls of produced water were released due to a water hauler driving off without disconnecting the load line. We were able to recover 1/4bbl of oil and 10bbls of produced water with a vacuum truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>		OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.		Approved by District Supervisor: <i>Harvey</i>	
Title: Senior Environmental Coordinator		Approval Date: 4-2-14	Expiration Date: NA
Email Address: rgrubbs@concho.com		Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 01-17-2014	Phone: 432-661-6601		

\* Attach Additional Sheets If Necessary


Accepted for record  
NMOCD

2RP-2245

**Bratcher, Mike, EMNRD**

---

**From:** Robert Grubbs <RGrubbs@concho.com>  
**Sent:** Monday, January 27, 2014 8:32 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Robert McNeill; Production Mail  
**Subject:** C-141 Initial/Final Report - Loco Hills SWD 35 #001 (SWD)  
**Attachments:** 01-17-2014 Loco Hills SWD 35 #001 (SWD) Initial - Final.pdf



**Mr. Bratcher,**

***Please see attached the C-141 Initial/Final Report for a release that occurred at our Loco Hills SWD 35 #001 (SWD) on 01-17-2014 in Eddy County New Mexico. This is a lined facility.***

***Thank you,***

***Robert Grubbs Jr.  
Sr. Environmental Coordinator  
432.683.7443 (main)  
432.818.2369 (direct)  
432.661.6601 (cell)  
[rgrubbs@concho.com](mailto:rgrubbs@concho.com)  
Mailing Address:  
One Concho Center  
600 W. Illinois Avenue  
Midland, Texas 79701***



***CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.***

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.