

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Pat Ellis</b>
Address <b>550 W. Texas, Suite 1300 Midland, Texas 79701</b>	Telephone No. <b>(432) 230-0077</b>
Facility Name <b>Antelope State Tank Battery</b>	Facility Type <b>Tank Battery</b>

Surface Owner: State	Mineral Owner	Lease No. <b>B-3627</b>
----------------------	---------------	-------------------------

**LOCATION OF RELEASE**

*30-015-32040*


Unit Letter <b>K</b>	Section <b>36</b>	Township <b>17S</b>	Range <b>31E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude N 32.78810° Longitude W 103.82630°

**NATURE OF RELEASE**

Type of Release: <b>Produced Fluid</b>	Volume of Release <b>15 bbls</b>	Volume Recovered <b>13 bbls</b>
Source of Release: <b>Equalizer</b>	Date and Hour of Occurrence <b>08/30/2011</b>	Date and Hour of Discovery <b>08/30/2011 11:00 a.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>N/A</b>	
If a Watercourse was Impacted, Describe Fully.*  <b>N/A</b>		
Describe Cause of Problem and Remedial Action Taken.*  <b>Water hauling company did not keep up with the water in tank, causing the tank to overflow.</b>		
Describe Area Affected and Cleanup Action Taken.*  <b>Tetra Tech inspected the site and assessed the spill area for extents. Work plan was submitted for the remediation of the soils. The soils exceeding RRAL and elevated chlorides were removed and transported to proper disposal. Once excavated, clay material was placed in the excavation bottom to cap the remaining impact and backfilled to grade. Tetra Tech prepared a closure report and submitted to the NMOCD for review.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

**OIL CONSERVATION DIVISION**

Signature: 	Approved by District Supervisor: 	
Printed Name: <b>Ike Tavarez (agent for COG)</b>	Approval Date: <b>4/24/14</b>	Expiration Date: <b>NA</b>
Title: <b>Project Manager</b>	Conditions of Approval: <b>Final</b>	
E-mail Address: <b>Ike.Tavarez@TetraTech.com</b>	Attached <input type="checkbox"/>	
Date: <b>5-10-12</b>	Phone: (432) 682-4559	

\* Attach Additional Sheets If Necessary

*2 RP-906*