


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

24669 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI EXPLORATION & PRODUCTION	Contact	BRANDON RIPLEY-PRODUCTION FOREMAN
Address	210 PARK AVE, STE 900, OKC, OK 73102	Telephone No.	575-689-5431, 575-885-1313
Facility Name	ROSS DRAW UNIT 11	Facility Type	TRANSFER LINE

Surface Owner	Mineral Owner	API No.	30-015-24307
---------------	---------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	22	26S	30E	660	SOUTH	1980	EAST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	WATER & OIL	Volume of Release	~200 BBLS	Volume Recovered	0 BBLS
Source of Release	PVC TRANSFER LINE	Date and Hour of Occurrence		Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	3/18/2014	3/18/2014 ~8:30 AM	
By Whom?	RICHARD DAVIS	Date and Hour	3/21/2014 8:30 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

4" PVC TRANSFER LINE LEAKED DUE TO A HOLE, THE LEAK RAN APPX. 6/10 OF A MILE WEST THROUGH A RAVINE

Describe Area Affected and Cleanup Action Taken.*

WAITING ON RECOMMENDATION

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Heather Brehm</i>	OIL CONSERVATION DIVISION	
Printed Name: HEATHER BREHM	Approved by Environmental Specialist: <i>Heather Brehm</i>	
Title: REGULATORY ANALYST	Approval Date: 5/2/14	Expiration Date: NA
E-mail Address: hbrehm@rkixp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/29/2014	Phone: 405-996-5769	

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NO LATER THAN:**

6/2/14

2PP-2286

Bratcher, Mike, EMNRD

From: Heather Brehm <HBrehm@rkixp.com>
Sent: Saturday, March 29, 2014 4:18 PM
To: shughes@blm.gov; Bratcher, Mike, EMNRD
Cc: Joe Massey
Subject: RDU 11_SPILL REPORT
Attachments: RDU 11_C-141-signed_3.29.14.pdf

Attached is the C-141 report for the Ross Draw Unit 11.

Unfortunately, I will be out for a couple weeks for a knee surgery. Please contact Joe Massey if there is any further information required at this time.

Sol, I have forwarded Joe the tracking information so he will be in the loop with you on that until I return. I am, of course, available by email if there are any questions.

Thank You,

Heather Brehm
Regulatory Analyst
RKI Exploration and Production
210 Park Ave, Suite 900
Oklahoma City, OK 73102
405-996-5769 office
405-949-2221 main

Patterson, Heather, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Monday, April 07, 2014 11:18 AM
To: Joe Massey; Heather Brehm
Cc: shughes@blm.gov; Patterson, Heather, EMNRD
Subject: RE: RDU 11_SPILL REPORT

Joe,

The C-141 indicates a release of oil and produced water, however it lists total fluid volume released. For data entry purposes, we need to have at least an estimate of how much of the release was oil and how much was PW.

Thanks

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

from: Heather Brehm [<mailto:HBrehm@rkixp.com>]
Sent: Saturday, March 29, 2014 4:18 PM
To: shughes@blm.gov; Bratcher, Mike, EMNRD
Cc: Joe Massey
Subject: RDU 11_SPILL REPORT

Attached is the C-141 report for the Ross Draw Unit 11.

Unfortunately, I will be out for a couple weeks for a knee surgery. Please contact Joe Massey if there is any further information required at this time.

Sol, I have forwarded Joe the tracking information so he will be in the loop with you on that until I return. I am, of course, available by email if there are any questions.

Thank You,

Heather Brehm
Regulatory Analyst
RKI Exploration and Production
210 Park Ave, Suite 900
Oklahoma City, OK 73102
405-996-5769 office
405-949-2221 main

Bratcher, Mike, EMNRD

From: Heather Brehm <HBrehm@rkixp.com>
Sent: Friday, May 02, 2014 9:01 AM
To: Bratcher, Mike, EMNRD; Joe Massey
Cc: shughes@blm.gov; Patterson, Heather, EMNRD
Subject: RE: RDU 11_SPILL REPORT

Unfortunately, Joe is no longer with RKI so I will continue to handle the Spill incidents. On that fluid breakdown I believe we were going to stick with the amount on the amended forms I most recently sent out.

Oil ~ 10 bbls

Water ~ 190 bbls

I am still waiting to hear back from Boone Archeological on their clean up recommendation. Hope this helps and please let me know if there is any additional information you need.

Heather Brehm
RKI

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]
Sent: Friday, May 02, 2014 9:32 AM
To: Joe Massey; Heather Brehm
Cc: shughes@blm.gov; Patterson, Heather, EMNRD
Subject: RE: RDU 11_SPILL REPORT

Joe,

Please provide the requested information, even if just an estimate. Your estimate will be closer than mine. Also, please provide an update as to the status of the remediation of this release.

Thank you,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Bratcher, Mike, EMNRD
Sent: Monday, April 07, 2014 11:18 AM
To: Joe Massey; 'Heather Brehm'
Cc: shughes@blm.gov; Patterson, Heather, EMNRD
Subject: RE: RDU 11_SPILL REPORT

Joe,

The C-141 indicates a release of oil and produced water, however it lists total fluid volume released. For data entry purposes, we need to have at least an estimate of how much of the release was oil and how much was PW.

Thanks

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

from: Heather Brehm [<mailto:HBrehm@rkixp.com>]
Sent: Saturday, March 29, 2014 4:18 PM
To: shughes@blm.gov; Bratcher, Mike, EMNRD
Cc: Joe Massey
Subject: RDU 11_SPILL REPORT

Attached is the C-141 report for the Ross Draw Unit 11.

Unfortunately, I will be out for a couple weeks for a knee surgery. Please contact Joe Massey if there is any further information required at this time.

Sol, I have forwarded Joe the tracking information so he will be in the loop with you on that until I return. I am, of course, available by email if there are any questions.

Thank You,

Heather Brehm
Regulatory Analyst
RKI Exploration and Production
210 Park Ave, Suite 900
Oklahoma City, OK 73102
405-996-5769 office
405-949-2221 main