

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, LP	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704, Carlsbad, NM 88220	Telephone No. (575)887-7329
Facility Name: PLU-49 2RP-2192	Facility Type: Exploration & Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-23430	


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	17	24S	30E	1980	North	990	West	Eddy

Latitude 32.219330° North Longitude 103.908958° West

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 20 bbls	Volume Recovered None
Source of Release Unauthorized dumping	Date and Hour of Occurrence 1/25/14 time unknown	Date and Hour of Discovery 1/25/14 at 2:30 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Jim Amos - BLM	
By Whom? Tony Savoie	Date and Hour 1/25/14 at 3:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* An unknown transport truck dumped the produced water on the PLU-49 well pad.

Describe Area Affected and Cleanup Action Taken.* The release impacted approximately 6,760 sq. ft. of the caliche pad. Remediation activities conducted at the PLU #49 Illegal Dump release site met the objectives set forth by the NMOCD and BLM. Soil samples collected from the excavation were analyzed by an NMOCD-approved laboratory, which determined concentrations of BTEX, TPH and chloride were less than NMOCD regulatory standards in each of the submitted soil samples, with the exception of soil samples NSW #1 (In-Situ), NSW #2 (In-Situ) and NSW #3. Further excavation to the north was limited since it was outside of the margins of the immediate illegal dump and led into a historic reserve pit. Please reference the attached *Remediation Summary and Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist	Approval Date: <u>5/5/14</u>	Expiration Date: <u>NA</u>
E-mail Address: tasavoie@basspet.com	Conditions of Approval: <u>Final</u>	
Date: <u>4/24/14</u> Phone: 432-556-8730	Attached <input type="checkbox"/>	

Attach Additional Sheets If Necessary