

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1413427828

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.

Contact: Brian Wall

Address: 2130 W. Bender Hobbs, NM 88240

Telephone No. 575-738-1739

Facility Name: Turner B #101

Facility Type: Injection

Surface Owner Federal

Mineral Owner Federal

API No. 30-015-26695

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
D	20	17S	31E	690	North	1150	West	

Latitude 32.8245657898873 Longitude -103.896766902005

NATURE OF RELEASE

Type of Release: Produced Water/Oil	Volume of Release 4 bbls/1 bbl	Volume Recovered 0
Source of Release: Poly Pipeline	Date and Hour of Occurrence 10/09/2013 12:00 P.M.	Date and Hour of Discovery 10/09/2013 12:00 P.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton BLM	
By Whom?	Date and Hour 10/15/13 11:45 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

RECEIVED

APR 29 2014

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

10-09-13 received phone call from an Apache pumper that there had been a poly line leak. Placed a temporary clamp on the line until a crew was available to bleed down the line and fuse it.

Describe Area Affected and Cleanup Action Taken.*

There was an approximate affected area of 40X20. There was a small misted area with a nominal amount of standing water. DFSI was retained to remediate the spill and reclaim the pad. On February 05, 2014 the site was reclaimed and seeded according to NMOCD and BLM guidelines. DFSI respectfully requests closure of this C-141.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: Fred B Wall

Printed Name: Brian Wall

Approved by Environmental Specialist:

Title: Construction Foreman II

Approval Date: 5/14/14

Expiration Date: NA

E-mail Address: bwall@linenergy.com

Conditions of Approval:

Attached ☐

Date: 03/25/2014

Phone: 806-367-0645

Final

* Attach Additional Sheets If Necessary

22P-2299