District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised October 10, 2003

MAY 1 9 2018 with 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

1220 S. St. Francis Dr., Santa Fe, NM 87505 Release Notification and Corrective Action nHmp 1414931417 **OPERATOR** Final Report Name of Company OGRID Number Contact Yates Petroleum Corporation Robert Asher 25575 Telephone No. Address 104 S. 4TH Street 575-748-1471 Facility Name API Number Facility Type Leonardo BKL Federal Com #1 30-015-22763 Battery Surface Owner Mineral Owner Lease No. Federal Federal NM-92167 LOCATION OF RELEASE Unit Letter Feet from the North/South Line East/West Line Section Township Range Feet from the County G 28 25S 27E 1980' North 1980' Eddy East Latitude 32.10274 Longitude 104.19242 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered 60 B/PW Produced Water 1/2 B/PW Source of Release Date and Hour of Occurrence Date and Hour of Discovery 5/4/2014; AM 5/4/2014; AM 8 inch water line Was Immediate Notice Given? If YES, To Whom? Mike Bratcher/NMOCD II By Whom? Date and Hour Robert Asher/Yates Petroléum Corporation 5/5/2014; AM (Email) Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Yes No If a Watercourse was Impacted, Describe Fully.* Describe Cause of Problem and Remedial Action Taken.* A 2 inch poly line riser on the water line ruptured, causing the release. Describe Area Affected and Cleanup Action Taken.* An approximate area of 100' X 100' (release was approximately 2500' north of the battery). The poly line was repaired, and vacuum trucks were called to recover the remaining produced water. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL a work plan will be submitted to the NMOCD. Depth to Ground Water: <25" (approximately 25', per the ChevronTexaco trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Approved by District Supervisor: Printed Name: Robert Asher 111 Title: NM Environmental Regulatory Supervisor Approval Date: Expiration Date:

* Attach Additional Sheets If Necessary

Date: Monday, May 19, 2014

E-mail Address: boba@yatespetroleum.com

Phone: 575-748-4217

PROPOSAL NO LATER THAN:

Remediation per OCD Rule & Guidelines, &

Conditions of Approval:

ZRP-2314

Attached

Bratcher, Mike, EMNRD

From:

Tanna Adams <TCAdams@yatespetroleum.com>

Sent:

Monday, May 19, 2014 4:36 PM

To:

Bratcher, Mike, EMNRD

Cc:

Bob Asher

Subject:

Leonardo BKL Federal Com #1

Attachments:

Leonardo.pdf

Attached is the signed C-141 for the Leonardo BKL Federal Com #1.

Thanks!

Tanna Adams

Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Bratcher, Mike, EMNRD

From:

Bob Asher <BobA@yatespetroleum.com>

Sent:

Monday, May 05, 2014 8:11 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD;

dwhitloc@blm.gov; jamos@blm.gov

Cc:

Amber Cannon; Chase Settle; Katie Parker; Manuel Gonzalez; Tanna Adams

Subject:

Release Notification (Leonardo BKL Federal Com. #1)

Yates Petroleum Corporation is reporting a release at the following location (5/4/2014; approximately 11:45 AM).

Leonardo BKL Federal Com. #1 30-015-22763 Section 28, T25S-R27E 1980 FNL & 1980 FEL Eddy County, New Mexico

Released: 60 B/PW; Recovered: 0 B/PW.

Release caused by main water line break approximately 0.25 miles north of the location. Vacuum truck(s) were called.

A Form C-141 Initial Report will be submitted with complete information.

Thank you.

Robert Asher

NM Environmental Regulatory Supervisor

Yates Petroleum Corporation

105 S. 4th Street , Artesia, NM 88210 575-748-4217 (Office) 575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

