

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

28P-2102

OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|---|
| Name of Company: BOPCO, LP | Contact: Tony Savoie |
| Address: 522 W. Mermod, Suite 704, Carlsbad, NM 88220 | Telephone No. (575)887-7329 |
| Facility Name: Poker Lake Unit Crude Oil Gathering System | Facility Type: Exploration & Production |
| Spill location 1400 ft. east of the PLU-227 Tank Battery | |

| | | |
|------------------------|------------------------|----------------------|
| Surface Owner: Federal | Mineral Owner: Federal | API No. 30-015-33929 |
|------------------------|------------------------|----------------------|

LOCATION OF RELEASE


| | | | | | | | | |
|------------------|---------------|-----------------|--------------|----------------------|---------------------------|----------------------|------------------------|----------------|
| Unit Letter M | Section 29 | Township 24S | Range 30E | Feet from the 118 | North/South Line South | Feet from the 836 | East/West Line West | County Eddy |
|------------------|---------------|-----------------|--------------|----------------------|---------------------------|----------------------|------------------------|----------------|

Latitude 32.181606° North Longitude 103.909504° West

NATURE OF RELEASE

| | | |
|--|--|--|
| Type of Release Crude oil | Volume of Release 270 bbls | Volume Recovered 220 bbls |
| Source of Release 6" Pipeline | Date and Hour of Occurrence 12/6/13 at 12:15 p.m. | Date and Hour of Discovery 12/6/13 12:15 p.m. |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? NMOCD Emergency #104 and the BLM | |
| By Whom? Tony Savoie | Date and Hour 12/6/13 NMOCD at 12:28 p.m. BLM 12:30 p.m. | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.* The 6" crude oil gathering line was struck and ruptured by a track-hoe operated by New Mexico Rental while excavating a line operated by Enterprise. Vacuum trucks were immediately dispatched to the spill location, LACT units were shut down, and the damaged section of pipe was isolated. The track-hoe excavated the damaged area, and a temporary repair clamp was used to stop the flow of oil. The line was permanently repaired on 12/7/13 by replacing the damaged section of pipe.

Describe Area Affected and Cleanup Action Taken.* The spill was contained within the excavation, which was in the middle of a lease road. The excavation measured approximately 30 ft. by 10 ft. by 6 ft. in depth. Approximately 220 bbls of crude oil was recovered from the excavation and placed back into the production facilities at the PLU-227 and PLU-213. The site was remediated as per NMOCD recommended guidelines and met the objectives set forth in the *Remediation Summary & Risk-Based Site Closure Proposal* dated December 2013. Please reference the attached *Remediation Summary & Site Closure Request* for remediation details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|--|---------------------------------------|---------------------|
| Signature: Tony Savoie | | OIL CONSERVATION DIVISION | |
| Printed Name: Tony Savoie | | Approved by Environmental Specialist: | |
| Title: Waste Management and Remediation Specialist | | Approval Date: 5/27/14 | Expiration Date: NA |
| E-mail Address: tasavoie@basspet.com | | Conditions of Approval: Final | |
| Date: 5/20/14 Phone: 432-556-8730 | | Attached <input type="checkbox"/> | |

* Attach Additional Sheets If Necessary