

**RECEIVED**

JAN 27 2014

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**NMOCD ARTESIA**

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action****OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company Apache Corporation	Contact Bruce Baker
Address P.O. Box 1849 Eunice, NM 88231	Telephone No. 432-631-6982
Facility Name Tony Federal #27	Facility Type Oil Well

Surface Owner BLM	Mineral Owner Federal	API No. 30-015-32753
-------------------	-----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter II	Section 19	Township 17S	Range 31E	Feet from the 1650	North/South Line FNL	Feet from the 990	East/West Line FEL	County Eddy
-------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude 32.82274 Longitude -103.90375

**NATURE OF RELEASE**

Type of Release Mixed Fluids	Volume of Release 4bbls oil & 15bbls water	Volume Recovered 1bbl oil & 10bbls water
Source of Release Stuffing Box	Date and Hour of Occurrence 7/1/13	Date and Hour of Discovery 8:00 am 7/1/13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher of NMOCD	
By Whom? RECS per Apache Corp.	Date and Hour 7/1/13 2:00pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The release occurred at the stuffing box on the well. A vacuum truck was mobilized to recover 1bbl of oil and 10bbls of produced water. Talon/LPE was contracted to conduct initial spill response activities, perform soil sampling and draft a remediation work plan.

Describe Area Affected and Cleanup Action Taken.\*

Upon approval of the remediation work plan from NMOCD and BLM Talon/LPE performed the remedial activities described in the work plan. A closure report documenting the activities that took place on this site will be submitted to the NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: *Bruce Baker*

Printed Name: Bruce Baker

Title: Field Tech

E-mail Address: larry.baker@apachecorp.com

Date: 1-27-14

Phone: 432-631-6982

Approved by Environmental Specialist: *[Signature]*

Approval Date: 5/15/14

Expiration Date: *NA*

Conditions of Approval:

*Final*

Attached ☐

\* Attach Additional Sheets If Necessary

2 RP-1711