

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

AUG 09 2011

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Apache Corporation	Contact	Natalie Gladden
Address	PO Box 1849 Eunice, NM 88231	Telephone No.	575-390-4186
Facility Name	South Lusk 34 Federal #006	Facility Type	Production well and battery

Surface Owner	Unknown	Mineral Owner	BLM	Lease No.	30-015-37681
---------------	---------	---------------	-----	-----------	-------------------------

30-025-37681

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	19S	32E	990'	FNL	990'	FEL	Lea

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10	Volume Recovered 5bbls
Source of Release Plunger failure	07/15/11 1030am	07/15/11 1030am
Was Immediate Notice Given? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required</div>	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input type="checkbox"/> No</div>	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

DTW = 295'

RECEIVED

JUL 29 2011

NMOCD ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

The plunger busted releasing the fluid inside the bermed facility. Plunger was repaired and standing fluid was recovered.

Describe Area Affected and Cleanup Action Taken.*

A boring rig will drill for depth to ground water if any and the contamination from inside the facility will be excavated to approx. 1.5' in depth. After water depth is determined then the job scope will be re-evaluated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Natalie Gladden</i>	OIL CONSERVATION DIVISION <i>Jeffrey LeKing</i> Approved by District Superintendent Environmental Specialist		
Printed Name: Natalie Gladden	Approval Date: 08/09/11	Expiration Date: 10/11/11	
Title: EHS Environmental Tech	Conditions of Approval: SUBMIT FINAL		Attached <input type="checkbox"/>
E-mail Address: natalie.gladden@apachecorp.com	10/11/11		IRP-06-14-3088
Date: 07/20/11 Phone: 575-390-4186			

* Attach Additional Sheets If Necessary

JUN 18 2014

NSAD 1416853 994